WE HAVE TRIED OUR BEST TO ENSURE THE ACCURACY OF THE INFORMATION LISTED BELOW, BUT MISTAKES DO HAPPEN. PRIOR TO PURCHASE, BUYER SHOULD VERIFY ALL THE OPTIONS LISTED BELOW TO BE ACCURATE. WE MAKE NO REPRESENTATION TO THE ACCURACY OF THIS INFORMATION.

FRED MARTIN SUPERSTORE

fredmartinsuperstore.com

FINANCING AVAILABLE!†

AutoCheck BUYBACK Protection

Request an AutoCheck© Vehicle History Report To See The Detailed History On Any Car, Truck, Van or SUV In Seconds!

LIFETIME LIMITED POWERTRAIN WARRANTY*

*SOME RESTRICTION APPLY SEE BELOW.

ALL TRADE-INS WELCOME!

2020 GMC Sierra 1500 AT4 4x4

Odometer: 86,547
Engine: EcoTec3 5.3L V8
Color: Onyx Black
Interior: Jet Black With Kalahari Accents Leather

Transmission: 10-Speed Automatic
VIN: 1GTR9EEDXLZ177791
Stock #: 1C263336BP
Drivetrain: 4WD

COMFORT EQUIPMENT AND ACCESSORIES

Safety

4-Wheel Disc Brakes
ABS brakes
Dual front impact airbags
Dual front side impact airbags
Front anti-roll bar
Front wheel independent suspension
Keyless Open & Start
Low tire pressure warning

Additional

AT4 PREMIUM PACKAGE
APPLE CARPLAY & ANDROID AUTO
NAVIGATION
4-WHEEL DRIVE
20" ALLOY WHEELS
FACTORY REMOTE START
WIRELESS CHARGING PAD
BOSE 7-SPEAKER PREMIUM AUDIO

Exterior

Delay-off headlights
Front fog lights
Fully automatic headlights
Perimeter Lighting
6" Rectangular Black Tubular Assist Steps (LPO)
Auto-dimming door mirrors
Body-Color Surround Grille
Bumpers: body-color

Electronic

Navigation System
6 Speakers
6-Speaker Audio System Feature
AM/FM radio: SiriusXM with 360L
HD Radio
Premium audio system: GMC Infotainment System
Premium Bose 7-Speaker Sound System

Technical

Electrical Lock Control Steering Column
Manual Tilt-Wheel & Telescoping Steering Column
Off-Road Suspension
Speed-sensing steering
Traction control
170 Amp Alternator
Auxiliary External Transmission Oil Cooler
High-Capacity Air Filter

Interior

Air Conditioning
Automatic temperature control
Electric Rear-Window Defogger
Front dual zone A/C
Rear window defroster
12-Volt Rear Auxiliary Power Outlet
120-Volt Bed Mounted Power Outlet
120-Volt Instrument Panel Power Outlet

GET PRE-QUALIFIED NOW!
THIS WILL NOT IMPACT OR EFFECT YOUR CREDIT SCORE!

For More Information, Check Out This Vehicle Online

NO-CHARGE EXTRAS!*

- 3 YEARS OF FREE OIL CHANGES*
- 15 DAY LOVE IT OR LEAVE IT RETURN GUARANTEE*
- 3 YEARS OF FREE ROADSIDE ASSISTANCE*
- FREE AUTOCHECK® VEHICLE HISTORY REPORT WITH BUYBACK PROTECTION*
- NO LEMON GUARANTEE*

IT IS THE RESPONSIBILITY OF THE PURCHASER TO VERIFY THE OPTIONS LISTED ON THIS LABEL ARE CORRECT PRIOR TO BUYING THIS VEHICLE. ALTHOUGH WE HAVE USED A COMPUTER SCREENING PROCESS TO ENSURE THE ACCURACY OF THIS LABEL THE PURCHASER MUST VERIFY THE EQUIPMENT LISTED ON THIS LABEL IS ACTUALLY ON THE VEHICLE, AS MISTAKES DO OCCUR. THE NO CHARGE ITEMS LISTED ABOVE AND AN * (ASTERISK) APPLY TO SELECT VEHICLES WITH A FINAL SELLING PRICE OF $12,000.00 OR ABOVE BEFORE TAX, TITLE, AND DOCUMENTARY FEE. EACH OF THE ITEMS LISTED WITH AN * (ASTERISK) HAVE A WRITTEN DOCUMENT DETAILING THEIR BENEFITS AND SHOULD BE READ AND UNDERSTOOD BY THE PURCHASER PRIOR THE PURCHASING THIS VEHICLE. † WITH APPROVED CREDIT.

Experian AutoCheck Report

Report run: 10/14/2026 11:34:05 EDT

This report is brought to you by:
Fred Martin Superstore ELITE MEMBER
3195 Barber Rd Norton, OH 44203
330.753.4444

2020 GMC Sierra 1500 AT4

Extended Cab 4D (5.3L V8 DI Gasoline)

VIN:	1GTR9EEDXLZ177791
Class:	Pickup - Fullsize
Country of Assembly:	United States
Vehicle Age:	6 year(s)
Estimated In Service:	02/13/2020
Last Reported Odometer:	86,546 (09/17/2026)

Owners - 2

Vehicle Usage

Lease, Livery

AutoCheck Score

87 **90** 92

Similar vehicles usually range between **87 and 92**

Vehicle History at a Glance

State Title Brand
✓ CLEAN

Auction Brand / Issues
✓ NO ISSUE

Accident / Damage
No Accidents or Damage Reported

✓ NO ISSUE

Open Recall Check
✓ NO OPEN RECALLS

Insurance Loss / Transfer
✓ NO ISSUE

Odometer Check
Last reported odometer:
86,546 (09/17/2026)

✓ NO ISSUE

Certified Pre-Owned
✓ NO CPO INFO AVAILABLE

Service / Repair
22 Service Record(s) Reported

✓ NO ISSUE

Additional History
Lien Reported

! EVENTS REPORTED

AutoCheck Assured

This vehicle is AutoCheck Assured™

This vehicle does not have any state title brands or other major problems reported.

Learn More

Accident & Damage

Your Vehicle Checks Out There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.



Airbag Deployed

Structural Damage

Overturned

No Damage

Service History

Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.

Regular Oil Changes
- 5 oil services reported
- Last oil service reported 08/27/2026

Fluids Maintained
- 1 coolant flushes
- Last fluid maintained 03/25/2024

Brakes Maintained
- 5 brake pad replacements
- Brake last maintained on 11/03/2025

Tires Maintained

Information not available.

A/C & Climate Control
- 2 A/C services reported
- A/C system last serviced 03/28/2024

Other Services
- Cabin air filter replaced on 04/14/2022

OEM Recommended Services

82500 Mile Service
- Change engine oil and filter
- Check accelerator pedal
- Check engine coolant and washer fluid

90000 Mile Service Not Yet Due
- Change engine oil and filter
- Check accelerator pedal
- Check engine coolant and washer fluid

Odometer Check

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

State Title Odometer Check

No issues reported

Auction Odometer Check

No issues reported

Odometer Calculation Check

No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2020 GMC Sierra 1500 AT4 (1GTR9EEDXLZ177791) **Report Run Date:** 10/14/2026 11:34:05 EDT

2020

Owner 1

Location: OH | Owned From: 02/2020 | Usage: Lease, Livery

Event Date	Location	Odometer	Data Source	Details
02/13/2020	AURORA, OH	361	Motor Vehicle Dept.	Title(Title #:7708264605) (Lien Reported) Livery Use
03/16/2020	AURORA, OH		Motor Vehicle Dept.	Registration Event/Renewal
11/02/2020	AURORA, OH		Motor Vehicle Dept.	Registration Event/Renewal
07/13/2021	OH	11,815	Service Record	Vehicle Inspected Vehicle Recall Service Performed Vehicle Detailed Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
08/09/2021	BURTON, OH	11,815	Motor Vehicle Dept.	Title(Title #:2800906097) (Leased Vehicle)

2021

Owner 2

Location: OH | Owned From: 09/2021 | Usage: Personal

Event Date	Location	Odometer	Data Source	Details
09/14/2021	CHARDON, OH	11,880	Motor Vehicle Dept.	Title(Title #:2800909671) (Lien Reported)
09/24/2021	OH	13,575	Service Record	Vehicle Inspected Brakes Serviced
10/08/2021	CHARDON, OH		Motor Vehicle Dept.	Registration Event/Renewal
03/03/2022	OH	21,648	Service Record	Fuel System Serviced Vehicle Inspected Tires or Wheels Service Performed
04/14/2022	OH	23,878	Service Record	Vehicle Inspected Air Filter Changed Exhaust System Serviced
04/21/2022	CHARDON, OH		Motor Vehicle Dept.	Registration Event/Renewal
04/29/2022	OH	24,378	Service Record	Vehicle Inspected Exhaust System Serviced Brakes Serviced
06/17/2022	OH	27,088	Service Record	Vehicle Inspected Wipers Replaced And/Or Serviced Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
04/21/2023	CHARDON, OH		Motor Vehicle Dept.	Registration Event/Renewal
03/07/2024	BURTON, OH	57,807	Service Record	Cooling System Serviced Multiple Point Vehicle Inspection Engine Serviced Exhaust System Serviced
03/13/2024	OH		Service Record	Vehicle Inspected Engine Serviced
03/25/2024	BURTON, OH	58,470	Service Record	Multiple Point Vehicle Inspection Engine Serviced Vehicle Fluids Serviced
03/28/2024	OH		Service Record	Cooling System Serviced Vehicle Inspected
04/06/2024	BURTON, OH	58,881	Service Record	Multiple Point Vehicle Inspection
04/11/2024	OH		Service Record	Vehicle Inspected Alternator Serviced
04/11/2024	BURTON, OH	58,884	Service Record	Vehicle Serviced or Inspected
04/19/2024	OH		Service Record	Vehicle Inspected Electrical System Serviced
04/22/2024	CHARDON, OH		Motor Vehicle Dept.	Registration Event/Renewal
04/22/2024	OH	59,000	Independent Emission Source	Passed Emission Inspection
04/29/2024	BURTON, OH	59,715	Service Record	Multiple Point Vehicle Inspection

Event Date	Location	Odometer	Data Source	Details
05/09/2024	BURTON, OH	59,999	Service Record	Multiple Point Vehicle Inspection Engine Serviced Exhaust System Serviced Electrical System Serviced
07/18/2024	OH		Service Record	Vehicle Inspected Engine Serviced
04/21/2025	CHARDON, OH		Motor Vehicle Dept.	Registration Event/Renewal
11/03/2025	OH	76,976	Service Record	Vehicle Detailed Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
01/05/2026	OH	79,273	Service Record	Vehicle Inspected Drive Line Serviced
04/20/2026	CHARDON, OH		Motor Vehicle Dept.	Registration Event/Renewal
04/20/2026	OH	83,000 †	Independent Emission Source	Passed Emission Inspection
04/22/2026	OH	82,126	Service Record	Vehicle Inspected Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
08/10/2026	OH		Service Record	Vehicle Serviced or Inspected
08/27/2026	OH	85,816	Service Record	Vehicle Inspected Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
09/17/2026	ONLINE DEALER	86,545	Dealer Listing	Vehicle Listed for Sale
09/17/2026	BARBERTON, OH	86,546	Dealer Listing	Vehicle Listed for Sale

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

Warranty Check

To see your estimated warranty coverage details, please enter a mileage reading below. The warranty coverage shown is an estimate using the best available in-service date, the mileage reading you enter, and warranty information. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to **AutoCheck Terms and Conditions**. If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.

Here is a list of some major defects that may occur in used vehicles.

Frame & Body
- Frame-cracks, corrective welds, or rusted through
- Dog tracks—bent or twisted frame

Engine
- Oil leakage, excluding normal seepage
- Cracked block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

Transmission & Drive Shaft
- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear
- Manual clutch slips or chatters

Differential
- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

Cooling System
- Leakage including radiator
- Improperly functioning water pump

Electrical System
- Battery leakage
- Improperly functioning alternator, generator, battery, or starter

Fuel System
- Visible leakage

Inoperable Accessories
- Gauges or warning devices
- Air conditioner
- Heater & Defroster

Brake System
- Failure warning light broken
- Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserve (DOT spec.)
- Does not stop vehicle in straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Structural or mechanical parts damaged

Air Bags

Steering System
- Too much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jams
- Front wheels aligned improperly (DOT specs.)
- Power unit belts cracked or slipping
- Power unit fluid level improper

Suspension System
- Ball joint seals damaged
- Structural parts bent or damaged
- Stabilizer bar disconnected
- Spring broken
- Shock absorber mounting loose
- Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

Tires
- Tread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

Wheels
- Visible cracks, damage or repairs
- Mounting bolts loose or missing

Exhaust System
- Leakage
- Catalytic Converter

Fred Martin Motor Company
DEALER NAME

3195 Barber Rd, Barberton, Ohio 44203
ADDRESS

(330) 753-4444
TELEPHONE

EMAIL

Sales Manager
FOR COMPLAINTS AFTER SALE, CONTACT:

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).

Trade In/Loan/Retail Breakdown
J.D. Power
Publication 10/2026, Region: Central

2020 GMC Sierra 1500 Extended Cab AT4 4WD 5.3L V8 ..... $30,475 / $27,450 / $35,975

VIN: 1GTR9EEDXLZ177791

Stock #: 1C263336BP

MSRP 51300
Weight 4835

*** Itemized Add/Deducts ***

Power Windows ..... Included
Power Door Locks ..... Included
Bose Premium Stereo ..... Included
Aluminum/Alloy Wheels ..... Included
Rear Parking Sensors ..... Included
Driver Alert 1 Pkg. ..... Included
W/out Driver Alert 2 Pkg. ..... -650 / -650 / -725
ProGrade Trailering Pkg. ..... Included
Towing/Camper Pkg ..... Included
Heated Exterior Mirrors ..... Included
Power Adjustable Mirrors ..... Included
Univ Garage Door Opener ..... Included
Navigation System ..... Included
Condition ..... Clean
Total Value without mileage ..... $29,825 / $26,800 / $35,250
Mileage adjustment (86547) miles $0

*** J.D. Power Trade In/Loan/Retail
$29,825 / $26,800 / $35,250

Fred Martin Motor Company - Deborh Regec

J.D. Power publication for Ohio: Publication 10/2026, Region: Central

Values are subjective opinions. J.D. Power and vAuto, Inc. assume no responsibility for errors or omissions.

© vAuto, Inc. 2026, all rights reserved.

Typical Listing Price/Trade In/Private Party/Fair Purchase Price Breakdown

KBB.com

10/14/2026 Edition 44203

2020 GMC Sierra 1500 Double Cab AT4 Pickup 4D 6 1/2 ft ..... $29,380 / $27,050 / $28,210 / $28,700

VIN: 1GTR9EEDXLZ177791

Stock #: 1C263336BP

*** Itemized Add/Deducts ***

V8, EcoTec3, DFM, 5.3 Liter	Included	AM/FM/HD Radio	Included
Automatic, 10-Spd w/Overdrive	Included	Premium Sound	Included
4WD	Included	SiriusXM Satellite	Included
Color: Black	20 / -60 / 20 / 20	Navigation System	Included
Driver Alert Pkg I	Included	Bluetooth Wireless	Included
Preferred Pkg	Included	OnStar	Included
Premium Pkg	Included	GMC Connected Access	Included
Hill Descent Control	Included	Premium GMC Infotainment System	Included
Hill Start Assist Control	Included	F&R Ultrasonic Park Assist	Included
Traction Control	Included	Backup Camera	Included
StabiliTrak	Included	Dual Air Bags	Included
ABS (4-Wheel)	Included	Side Air Bags	Included
Anti-Theft System	Included	F&R Head Curtain Air Bags	Included
Keyless Entry	Included	Heated Seats	Included
Keyless Start	Included	Ventilated Seats	Included
Air Conditioning	Included	Dual Power Seats	Included
Power Windows	Included	Leather	Included
Power Door Locks	Included	Daytime Running Lights	Included
Cruise Control	Included	LED Headlamps	Included
Power Tailgate Release	Included	Fog Lights	Included
Power Steering	Included	Towing Pkg	Included
Tilt & Telescoping Wheel	Included	Oversized Premium Wheels 20"+	327 / 327 / 327 / 327

Condition ..... Excellent*

Total Value without mileage ..... $29,727 / $27,317 / $28,557 / $29,047

Mileage adjustment (86547) miles $1,290

*** KBB.com Typical Listing Price/Trade In/Private Party/Fair Purchase Price
$31,017 / $28,607 / $29,847 / $30,337

*"Excellent" - 3% of all cars we value meet this criteria. This car looks new and is in excellent mechanical condition. It has never had paint or bodywork and has an interior and body free of wear and visible defects. The car is rust-free and does not need reconditioning. Its clean engine

compartment is free of fluid leaks. It also has a clean title history, has complete and verifiable service records.

Fred Martin Motor Company - Deborh Regec

©2026 Kelley Blue Book Co, Inc. All rights reserved. As of 10/14/2026 Edition for 44203. Values and pricing are the opinion of Kelley Blue Book, and the actual price of a vehicle may vary. The value and pricing information displayed for a particular vehicle is based upon the specification, mileage and/or condition information provided by the person generating this report. Kelley Blue Book assume no responsibility for errors or omissions.

© vAuto, Inc. 2026, all rights reserved.

CUSTOMER #: **727171**

INTERNAL

PAGE 1

FRED MARTIN SUPERSTORE
3195 Barber Road
Barberton, Ohio 44203-1011
(330) 753-4444
Fax (330) 753-2940
FCA 26453

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 7481 TROY DITTEMORE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
	20	GMC SIERRA 1500	1GTR9EEDXLZ177791		86546/86547	63336B

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			18:00 24SEP26		0.00	CASH	25SEP26

R.O. OPENED	READY	OPTIONS:
15:29 18SEP26	14:53 25SEP26	STK:1C263336BP DLR:FMMC-S ENG:5.3_Liter

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
A PREMIUM OIL AND FILTER CHANGE TOP OFF ALL FLUID LEVELS AND RESET TIRE PRESSURES			
NWD NO WORK DONE			
999 IUT 0.00		0.00	0.00
86546 0.00 lof was declined			
**********			
B Vehicle Inspection			
SAF Vehicle Inspection			
8144 IUT 1.00		120.00	120.00
4 WW WHEEL WEIGHT	1.35	1.35	5.40
4 TIRE DISPOSAL	2.85	2.85	11.40
2 SB582457 ROTOR	75.00	75.00	150.00
1 QX2174 PADS	75.00	75.00	75.00
1 ES801532 RF TIE ROD	203.69	142.10	142.10
4 MAS2756020 STRATUS HT	206.00	206.00	824.00
4 TIRE DISPOSAL	2.85	2.85	11.40
1 124606 LR CALIPER	1242.75	93.65	93.65
1 124607 RR CALIPER	124.75	93.65	93.65
1 4549625AF FLUID-BRAKE	17.62	17.62	17.62
86546 1.00 inspec			
**********			
C INFO			
INFO INFO			
8144 IUT 0.00		0.00	0.00
**********			
D** replace RF outer tierod			
800 REPLACE RF OUTER TIEROD			
8144 IUT 0.80		96.00	96.00
86546 0.80 replaced RF outer tierod			
**********			
E TWO AND OR FOUR WHEEL ALIGNMENT USED CARS			
UALIGN TWO AND OR FOUR WHEEL ALIGNMENT USED CARS			
8144 IUT 1.80		119.95	119.95
86546 1.80 4 wheel alignment			

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

Disclaimer of Warranties Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2C - IMAGING

INTERNAL COPY

CUSTOMER #: **727171**

INTERNAL

PAGE 2

FRED MARTIN SUPERSTORE
3195 Barber Road
Barberton, Ohio 44203-1011
(330) 753-4444
Fax (330) 753-2940
FCA 26453

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 7481 TROY DITTEMORE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
	20	GMC SIERRA 1500	1GTR9EEDXLZ177791		86546/86547	63336B

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			18:00 24SEP26		0.00	CASH	25SEP26

R.O. OPENED	READY	OPTIONS:
15:29 18SEP26	14:53 25SEP26	STK:1C263336BP DLR:FMMC-S ENG:5.3_Liter

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
F MISCELLANEOUS MECHANICAL			
MB4 MOUNT AND BALANCE FOUR NEW TIRES			
8144 IUT 1.20		140.00	140.00
86546 1.20 mount balanced 4 tires			
**********			
G REAR BRAKE PAD AND ROTOR REPLACEMENT			
RBN REAR BRAKE PAD AND ROTOR REPLACEMENT			
8144 IUT 1.50		180.00	180.00
86546 1.50 replaced rear pads and rotors			
**********			
H** replace both rear calipers			
800 replace both rear calipers			
8144 IUT 1.00		120.00	120.00
86546 1.00 replaced both rear calipers			
**********			
**********			
ESTIMATE: 0.00 21SEP26 07:46 SA: 7481			
CONTACT:			
**********			
SHOP SUPPLIES			20.00

SCHEDULE YOUR NEXT SERVICE ONLINE AT
WWW.FREDMARTINSUPERSTORE.COM AND GET $5.00
OFF THAT VISIT

COST, SALE, & COMP TOTALS 132585 220017 0

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

Disclaimer of Warranties Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

DESCRIPTION	TOTALS
LABOR AMOUNT	775.95
PARTS AMOUNT	1424.22
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	20.00
TOTAL CHARGES	2220.17
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	2220.17

Copyright 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2C - IMAGING

INTERNAL COPY

2020 GMC Sierra 1500

LARGE PICKUP / CREW CAB PICKUP



2019 GMC Sierra 1500 shown

Crashworthiness

Small overlap front: driver-side	G
Small overlap front: passenger-side	M
Moderate overlap front: original test	G
Side: original test	G
Side: updated test	A
Roof strength	G
Head restraints & seats	G

Crash avoidance & mitigation

Headlights	P

Front crash prevention: vehicle-to-vehicle

Optional system

Seat belts & child restraints

LATCH ease of use	M

Other available safety features

- Optional blind spot detection
- Optional lane departure warning

- Optional lane departure prevention

Key

G	Good	Superior
A	Acceptable	Advanced
M	Marginal	Basic
P	Poor	

Some ratings use a scale of Poor to Good. Others range from Basic to Superior.

Small overlap front: driver-side

Tested vehicle: **2019 Chevrolet Silverado 1500 LT Crew Cab 2wd**

Rating applies to 2019-26 models

The Chevrolet Silverado 1500 and GMC Sierra 1500 Crew Cab were redesigned for the 2019 model year.

Overall evaluation	**G**
Structure and safety cage	**A**
Driver injury measures	
Head/neck	**G**
Chest	**G**
Hip/thigh	**G**
Lower leg/foot	**A**
Driver restraints and dummy kinematics	**G**



Action shot taken during the driver-side small overlap frontal crash test.



The dummy's position in relation to the door frame, steering wheel, and instrument panel after the crash test indicates that the driver's survival space was maintained reasonably well.



The frontal and side curtain airbags worked well together to keep the head from coming close to any stiff structure or outside objects that could cause injury.



Intrusion of the toepan contributed to a moderate risk of injuries to the left foot and right lower leg.

▶ Technical measurements for this test

Small overlap front: passenger-side

Tested vehicle: **2019 Chevrolet Silverado 1500 LT Crew Cab 2wd**

Rating applies to 2019-26 models

The Chevrolet Silverado 1500 and GMC Sierra 1500 Crew Cab was redesigned for the 2019 model year.

Overall evaluation	**M**
Structure and safety cage	**P**
Passenger injury measures	
Head/neck	**G**
Chest	**G**
Hip/thigh	**G**
Lower leg/foot	**M**
Passenger restraints and dummy kinematics	**G**
Driver injury measures	
Head/neck	**G**
Chest	**G**
Hip/thigh	**G**
Lower leg/foot	**G**
Driver restraints and dummy kinematics	**G**



Action shot taken during the passenger-side small overlap frontal crash test.



The dummy's position in relation to the door frame and dashboard after the crash test indicates that the passenger's survival space was not maintained well.



The frontal and side curtain airbags worked well together to keep the passenger dummy's head from coming close to any stiff structure or outside objects that could cause injury.



Extensive intrusion of the dashboard, toepan, and door hinge pillar contributed to a significant risk of injury to the right lower leg and a moderate risk to the left lower leg.

▶ Technical measurements for this test

Moderate overlap front: original test

Tested vehicle: **2019 Chevrolet Silverado 1500 LT Crew Cab 2wd**

Rating applies to 2019-25 models

The Chevrolet Silverado 1500 and GMC Sierra 1500 Crew Cab were redesigned for the 2019 model year. Moderate overlap frontal ratings are assigned by the Institute based on a test conducted by General Motors.

Overall evaluation	**G**
Structure and safety cage	**G**
Driver injury measures	
Head/neck	**G**
Chest	**G**
Leg/foot, left	**G**
Leg/foot, right	**A**
Driver restraints and dummy kinematics	**G**

▶ Technical measurements for this test

Side: original test

Tested vehicle: **2019 Chevrolet Silverado 1500 LT Crew Cab 2wd**
Rating applies to 2019-25 models

The Chevrolet Silverado 1500 and GMC Sierra 1500 Crew Cab were redesigned for the 2019 model year. Side ratings are assigned by the Institute based on a test conducted by General Motors.

Overall evaluation	**G**
Structure and safety cage	**G**
Driver injury measures	
Head/neck	**G**
Torso	**G**
Pelvis/leg	**G**
Driver head protection	**G**
Rear passenger injury measures	
Head/neck	**G**
Torso	**G**
Pelvis/leg	**G**

Rear passenger head protection	**G**

▶ Technical measurements for this test

Side: updated test

Tested vehicle: **2023 Chevrolet Silverado 1500 LT Crew Cab 4wd**

Rating applies to 2019-26 models

The Chevrolet Silverado 1500 and GMC Sierra 1500 Crew Cab were redesigned for the 2019 model year. Two tests of the Silverado were conducted because the rear passenger data acquisition system failed during the first test. Driver dummy injuries, rear dummy restraints and kinematics and structural ratings are based on both tests. The rear dummy injury values are based only on the second test.

Overall evaluation	**A**
Structure and safety cage	**G**
Driver injury measures	
Head/neck	**G**
Torso	**G**
Pelvis	**G**
Driver head protection	**G**
Rear passenger injury measures	
Head/neck	**G**
Torso	**M**
Pelvis	**G**
Rear passenger head protection	**G**



View of the vehicle just after the crash test.



View of the vehicle after the crash with doors removed, showing the side airbags and damage to the occupant compartment.



Smeared greasepaint shows where the driver dummy's head was protected from being hit by hard structures by the side airbags.



Smeared greasepaint shows where the rear passenger dummy's head was protected by the side airbag. The C-pillar trim became completely dislodged during the crash.

▶ Technical measurements for this test

Roof strength

Tested vehicle: **2019 Chevrolet Silverado 1500 LTZ Crew Cab 2wd**

Rating applies to 2019-23 models

Overall evaluation	**G**
Curb weight	4,818 lbs
Peak force	22,236 lbs
Strength-to-weight ratio	4.62

Head restraints & seats

Seat type: **Power leather seat**

Overall evaluation	**G**
Dynamic rating	**G**
Seat/head restraint geometry	**G**

▶ Technical measurements for this test


Headlights

Ratings are given for **3 different headlight variations** available on this vehicle.

(1) Trim level(s): SLT trim equipped with Driver Alert II package, AT4 trim equipped with Driver Alert II package, Denali trim equipped with Driver Alert II package

Low-beam headlight type	LED reflector
High-beam headlight type	LED reflector
Curve-adaptive?	No
High-beam assist?	Yes
Overall rating	**P**

Distance at which headlights provide at least 5 lux illumination:



Low beams
On the straightaway, visibility was good on the left side of the road and fair on the right side. On curves, visibility was inadequate in all 4 tests.

The low beams created some glare.

High beams
On the straightaway, visibility was fair on the right side of the road and inadequate on the left side. On curves, visibility was inadequate in all 4 tests.


High-beam assist compensates for some limitations of this vehicle's low beams on the straightaway, on both left curves and on both right curves.

▶ Technical measurements for this test

(2) Trim level(s): SLT trim, AT4 trim, Denali trim

Low-beam headlight type	LED reflector
High-beam headlight type	LED reflector
Curve-adaptive?	No
High-beam assist?	No
Overall rating	**P**

Distance at which headlights provide at least 5 lux illumination:



Low beams
On the straightaway, visibility was good on the left side of the road and fair on the right side. On curves, visibility was inadequate in all 4 tests.

The low beams created some glare.


High beams
On the straightaway, visibility was fair on the right side of the road and inadequate on the left side. On curves, visibility was inadequate in all 4 tests.

▶ Technical measurements for this test

(3) Trim level(s): Sierra trim, SLE trim, Elevation trim

Low-beam headlight type	LED reflector
High-beam headlight type	LED reflector
Curve-adaptive?	No
High-beam assist?	No
Overall rating	**P**

Distance at which headlights provide at least 5 lux illumination:



Low beams

On the straightaway, visibility was fair on both sides of the road. On curves, visibility was fair on both right curves and inadequate on both left curves.

The low beams created some glare.

High beams

On the straightaway, visibility was inadequate on both sides of the road. On curves, visibility was inadequate in all 4 tests.

▶ Technical measurements for this test

Front crash prevention: vehicle-to-vehicle

System details

- optional Automatic Emergency Braking
- optional Forward Collision Alert

Package name

- optional Driver Alert package II package available on SLT, AT4, and Denali CC trims

Overall evaluation

SUPERIOR
WITH OPTIONAL EQUIPMENT

Applies to 2020 models


- This system meets the requirements for forward collision warning.
- In the 12 mph test, this vehicle avoided a collision.
- In the 25 mph test, this vehicle avoided a collision.

Child seat anchors

Rating applies to 2019-26 models

Overall evaluation	**M**
Vehicle trim	Denali
Seat type	leather

This vehicle has 2 rear seating positions with complete child seat attachment (LATCH) hardware. It has 1 additional seating position with a tether anchor only.



G	Good
A	Acceptable
M	Marginal
P	Poor
☐	Seating positions that rely on borrowed lower anchors or have only a tether anchor available

Details by seating position

1 **Tether anchor**

hard-to-find location

other hardware could be confused for anchor

Lower anchors

too deep in seat

not too much force needed to attach

easy to maneuver around anchors

2 **Tether anchor**

hard-to-find location

other hardware could be confused for anchor

Lower anchors

none available

3 **Tether anchor**

are not rated.

Tether anchor

Lower anchors

Lower anchor(s) can be borrowed from adjacent positions(s)

No hardware available

hard-to-find location

other hardware could be confused for anchor

Lower anchors

too deep in seat

not too much force needed to attach

easy to maneuver around anchors

▶ Technical measurements for this test

Making roads and vehicles safer for everyone.

The **Insurance Institute for Highway Safety (IIHS)** is an independent, nonprofit scientific and educational organization dedicated to reducing deaths, injuries and property damage from motor vehicle crashes through research and evaluation and through education of consumers, policymakers and safety professionals.

The **Highway Loss Data Institute (HLDI)** shares and supports this mission through scientific studies of insurance data representing the human and economic losses resulting from the ownership and operation of different types of vehicles and by publishing insurance loss results by vehicle make and model.

Both organizations are wholly supported by these auto insurers and insurance associations.

©1996-2026, Insurance Institute for Highway Safety, Highway Loss Data Institute, 501(c)(3) organizations | Copyright information and privacy policy