

WE HAVE TRIED OUR BEST TO ENSURE THE ACCURACY OF THE INFORMATION LISTED BELOW, BUT MISTAKES DO HAPPEN. PRIOR TO PURCHASE, BUYER SHOULD VERIFY ALL THE OPTIONS LISTED BELOW TO BE ACCURATE. WE MAKE NO REPRESENTATION TO THE ACCURACY OF THIS INFORMATION.

FRED MARTIN SUPERSTORE

fredmartinsuperstore.com

**FINANCING
AVAILABLE!†**

AutoCheck
BUYBACK
Protection

Request an AutoCheck®
Vehicle History Report To See
The Detailed History On Any Car,
Truck, Van or SUV In Seconds!



**LIFETIME LIMITED
POWERTRAIN WARRANTY***

*SOME RESTRICTIONS APPLY SEE BELOW.

**ALL
TRADE-INS
WELCOME!**

2019 Jeep Compass Latitude

Odometer: 66,882
Engine: 2.4L I4 MultiAir
Color: Granite Crystal Metallic Clearcoat
Interior: Black Cloth

Transmission: 6-Speed Aisin Automatic
VIN: 3C4NJCBB8KT676592
Stock #: 1C261970AV
Drivetrain: FWD

COMFORT EQUIPMENT AND ACCESSORIES

Technical

Four wheel independent suspension
Traction control

Interior

Air Conditioning
Automatic temperature control
Front dual zone A/C
Rear window defroster
Power steering
Power windows
Remote keyless entry
Steering wheel mounted audio controls
Speed control
Compass

Exterior

Delay-off headlights
Front fog lights
Fully automatic headlights

Bumpers: body-color
Heated door mirrors
Power door mirrors
Roof rack: rails only
Spoiler
Alloy wheels
Wheels: 17" x 7.0" Silver Painted
Aluminum
Rear window wiper

Electronic

6 Speakers
AM/FM radio
Bluetooth® Streaming Audio
Media Hub (USB, AUX)
Radio: Uconnect 4 w/7" Display

Safety

4-Wheel Disc Brakes
ABS brakes
Anti-whiplash front head restraints
Dual front impact airbags

Dual front side impact airbags
Front anti-roll bar
Knee airbag
Low tire pressure warning
Occupant sensing airbag
Overhead airbag

Additional

CITY MPG: 22 HIGHWAY MPG: 31
17" ALLOY WHEELS
FOG/CORNERING LAMPS
APPLE CARPLAY & ANDROID AUTO
2.4L I-4 MULTI-AIR ENGINE
6-SPEED AUTO TRANSMISSION
7" TOUCH SCREEN
BLUETOOTH PHONE & AUDIO
6-SPEAKER SOUND SYSTEM
STEERING WHEEL AUDIO CONTROLS
FRONT BUCKET SEATS



GET PRE-QUALIFIED NOW!

THIS WILL NOT IMPACT OR EFFECT YOUR CREDIT SCORE!

For More Information, Check Out This Vehicle Online



NO-CHARGE EXTRAS!*



**3 YEARS OF FREE
OIL CHANGES**



**15 DAY
LOVE IT OR LEAVE IT
RETURN GUARANTEE**



**3 YEARS OF FREE
ROADSIDE ASSISTANCE**



**FREE AUTOCHECK®
VEHICLE HISTORY REPORT
WITH BUYBACK PROTECTION**



**NO LEMON
GUARANTEE**

IT IS THE RESPONSIBILITY OF THE PURCHASER TO VERIFY THE OPTIONS LISTED ON THIS LABEL ARE CORRECT PRIOR TO BUYING THIS VEHICLE. ALTHOUGH WE HAVE USED A COMPUTER SCREENING PROCESS TO ENSURE THE ACCURACY OF THIS LABEL THE PURCHASER MUST VERIFY THE EQUIPMENT LISTED ON THIS LABEL IS ACTUALLY ON THE VEHICLE, AS MISTAKES DO OCCUR. THE NO CHARGE ITEMS LISTED ABOVE AND AN * (ASTERISK) APPLY TO SELECT VEHICLES WITH A FINAL SELLING PRICE OF \$12,000.00 OR ABOVE BEFORE TAX, TITLE, AND DOCUMENTARY FEE. EACH OF THE ITEMS LISTED WITH AN * (ASTERISK) HAVE A WRITTEN DOCUMENT DETAILING THEIR BENEFITS AND SHOULD BE READ AND UNDERSTOOD BY THE PURCHASER PRIOR THE PURCHASING THIS VEHICLE. † WITH APPROVED CREDIT.

Experian AutoCheck Report

Report run: 05/18/2026 14:58:58 EDT

This report is brought to you by:

Fred Martin Superstore **ELITE MEMBER**

3195 Barber Rd Norton, OH 44203

330.753.4444


2019 Jeep Compass Altitude / Latitude / Sun and Wheel Edition

SUV 4D (2.4L I4 SMPI Gasoline)

VIN:	3C4NJCBB8KT676592
Class:	CUV - Compact
Country of Assembly:	Mexico
Vehicle Age:	7 year(s)
Estimated In Service:	04/11/2019
Last Reported Odometer:	66,882 (05/11/2026)



Vehicle Usage
Lease



Vehicle History at a Glance

<p>State Title Brand</p> <p>CLEAN</p>	<p>Auction Brand / Issues</p> <p>NO ISSUE</p>	<p>Accident / Damage</p> <p>DAMAGE REPORTED</p>
<p>Open Recall Check</p> <p>NO OPEN RECALLS</p>	<p>Insurance Loss / Transfer</p> <p>NO ISSUE</p>	<p>Odometer Check Last reported odometer: 66,882 (05/11/2026)</p> <p>NO ISSUE</p>
<p>Certified Pre-Owned</p> <p>NO CPO INFO AVAILABLE</p>	<p>Service / Repair 1 Service Record(s) Reported</p> <p>NO ISSUE</p>	<p>Additional History Lien Reported</p> <p>EVENTS REPORTED</p>




This vehicle is AutoCheck Assured™

This vehicle does not have any state title brands or other major problems reported.

[Learn More](#)

Accident & Damage



Airbag Deployed



Structural Damage



Overturned



Unknown

Damage Date

Damage Type

Severity

05/11/2023

Collision

Unknown

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.

Recommended Maintenance

OEM Recommended Maintenance Schedule

Based on your vehicle's last reported mileage, these are the most recent and upcoming recommended maintenance intervals from your vehicle's manufacturer.

OEM Recommended Services



60000 Mile Service

- Change engine oil and engine oil filter
- Inspect battery and clean and tighten terminals as required
- Inspect brake linings



70000 Mile Service Not Yet Due

- Change engine oil and engine oil filter
- Inspect battery and clean and tighten terminals as required
- Inspect brake pads, shoes, rotors, drums, hoses



80000 Mile Service Not Yet Due

- Change engine oil and engine oil filter
- Inspect battery and clean and tighten terminals as required
- Inspect brake linings

Odometer Check



Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2019 Jeep Compass Altitude / Latitude / Sun and Wheel Edition (3C4NJCBB8KT676592) Report Run Date: 05/18/2026 14:58:58 EDT

2019

Owner 1

Location: FL

Owned From: 04/2019












Usage: Lease

Event Date	Location	Odometer	Data Source	Details
04/11/2019	FL	123	Motor Vehicle Dept.	Title(Leased Vehicle)(Lien Reported)
04/11/2019	PORT SAINT LUCIE, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
04/30/2019	FL		Motor Vehicle Dept.	Title(Leased Vehicle)(Lien Reported)
10/10/2019	PORT SAINT LUCIE, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
10/16/2020	PORT SAINT LUCIE, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
10/12/2021	PORT SAINT LUCIE, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
11/22/2022	PORT SAINT LUCIE, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
04/04/2023	FL	34,141	Motor Vehicle Dept.	Odometer Reading from DMV
04/04/2023	PORT SAINT LUCIE, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
05/11/2023	FL		Police Report	Right Front Impact with Another Vehicle Accident Reported(Report #:2305736) Vehicle Was Towed
06/28/2023	PORT SAINT LUCIE, FL		Motor Vehicle Dept.	Title(Leased Vehicle)(Lien Reported)
11/16/2023	PORT SAINT LUCIE, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
10/08/2024	PORT SAINT LUCIE, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
10/29/2025	PORT SAINT LUCIE, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
04/23/2026	MO	66,879	Auto Auction	Reported at Auto Auction
04/25/2026	ONLINE DEALER	66,879 †	Dealer Listing	Vehicle Listed for Sale
05/01/2026	FL	66,821 †	Service Record	Vehicle Inspected
05/11/2026	BARBERTON, OH	66,882	Dealer Listing	Vehicle Listed for Sale

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

Warranty Check

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic 	-	-		36 months / 36000 miles
Battery 	-	-	-	Contact a certified dealer to verify coverage
Corrosion 	-	-		60 months / Unlimited miles Outer Panel Corrosion Warranty. All panels are covered for 3 years/unlimited miles.
Powertrain 	-	-		60 months / 60000 miles
Roadside Assistance 	-	-		60 months / 60000 miles
Safety Restraint 	-	35 months		120 months / Unlimited miles For vehicles sold and registered in the State of Kansas, seatbelts and related seatbelt components are warranted against defects in workmanship and materials.

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.

Here is a list of some major defects that may occur in used vehicles.

Frame & Body

Frame-cracks, corrective welds, or rusted through
Dog tracks—bent or twisted frame

Engine

Oil leakage, excluding normal seepage
Cracked block or head
Belts missing or inoperable
Knocks or misses related to camshaft lifters and push rods
Abnormal exhaust discharge

Transmission & Drive Shaft

Improper fluid level or leakage, excluding normal seepage
Cracked or damaged case which is visible
Abnormal noise or vibration caused by faulty transmission or drive shaft
Improper shifting or functioning in any gear
Manual clutch slips or chatters

Differential

Improper fluid level or leakage, excluding normal seepage
Cracked or damaged housing which is visible
Abnormal noise or vibration caused by faulty differential

Cooling System

Leakage including radiator
Improperly functioning water pump

Electrical System

Battery leakage
Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories

Gauges or warning devices
Air conditioner
Heater & Defroster

Brake System

Failure warning light broken
Pedal not firm under pressure (DOT spec.)
Not enough pedal reserve (DOT spec.)
Does not stop vehicle in straight line (DOT spec.)
Hoses damaged
Drum or rotor too thin (Mfgr. Specs)
Lining or pad thickness less than 1/32 inch
Power unit not operating or leaking
Structural or mechanical parts damaged

Air Bags

Steering System

Too much free play at steering wheel (DOT specs.)
Free play in linkage more than 1/4 inch
Steering gear binds or jams
Front wheels aligned improperly (DOT specs.)
Power unit belts cracked or slipping
Power unit fluid level improper

Suspension System

Ball joint seals damaged
Structural parts bent or damaged
Stabilizer bar disconnected
Spring broken
Shock absorber mounting loose
Rubber bushings damaged or missing
Radius rod damaged or missing
Shock absorber leaking or functioning improperly

Tires

Tread depth less than 2/32 inch
Sizes mismatched
Visible damage

Wheels

Visible cracks, damage or repairs
Mounting bolts loose or missing

Exhaust System

Leakage
Catalytic Converter

Fred Martin Motor Company

DEALER NAME

3195 Barber Rd, Barberton, Ohio 44203

ADDRESS

(877) 644-5337

TELEPHONE

EMAIL

Sales Manager

FOR COMPLAINTS AFTER SALE, CONTACT:

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).

Trade In/Loan/Retail Breakdown

J.D. Power

Publication 05/2026, Region: Central

2019 JEEP Compass Utility 4D Latitude 2.4L I4..... \$9,950 / \$8,975 / \$14,425

VIN: 3C4NJCBB8KT676592

Stock #: 1C261970AV

MSRP..... 25345

Weight..... 3184

*** Itemized Add/Deducts ***

W/out Blind Spot Monitor..... -50 / -50 / -50

W/out Heated Front Seats..... -150 / -150 / -175

W/out Rear Parking Sensors..... -75 / -75 / -75

W/out Remote Engine Starter..... -75 / -75 / -75

W/out Navigation System..... -150 / -150 / -175

Condition..... Clean

Total Value without mileage..... \$9,450 / \$8,475 / \$13,875

Mileage adjustment (66882) miles..... \$2,225

*** J.D. Power Trade In/Loan/Retail
\$11,675 / \$10,700 / \$16,100

Fred Martin Motor Company - Tammy Carrico

Typical Listing Price/Trade In/Private Party/Fair Purchase Price Breakdown

KBB.com
05/18/2026 Edition 44203

2019 Jeep Compass Latitude Sport Utility 4D..... \$13,570 / \$8,965 / \$12,500 / \$12,790

VIN: 3C4NJCBB8KT676592
Stock #: 1C261970AV

***** Itemized Add/Deducts *****

4-Cyl, MultiAir, PZEV, 2.4 Lite	Included	Tilt & Telescoping Wheel.....	Included
Automatic, 6-Spd.....	Included	AM/FM Stereo.....	Included
FWD.....	Included	SiriusXM Satellite.....	Included
Hill Start Assist Control.....	Included	Bluetooth Wireless.....	Included
Traction Control.....	Included	Uconnect.....	Included
Electronic Stability Control....	Included	Backup Camera.....	Included
ABS (4-Wheel).....	Included	Dual Air Bags.....	Included
Keyless Entry.....	Included	Side Air Bags.....	Included
Push Button Start.....	Included	F&R Head Curtain Air Bags...	Included
Air Conditioning.....	Included	Knee Air Bags.....	Included
Power Windows.....	Included	Daytime Running Lights.....	Included
Power Door Locks.....	Included	Fog Lights.....	Included
Cruise Control.....	Included	Alloy Wheels.....	Included
Power Steering.....	Included		

Condition..... Excellent*
 Total Value without mileage..... \$13,570 / \$8,965 / \$12,500 / \$12,790
 Mileage adjustment (66882) miles..... \$2,320

***** KBB.com Typical Listing Price/Trade In/Private Party/Fair Purchase Price**
\$15,890 / \$11,285 / \$14,820 / \$15,110

*"Excellent" - 3% of all cars we value meet this criteria. This car looks new and is in excellent mechanical condition. It has never had paint or bodywork and has an interior and body free of wear and visible defects. The car is rust-free and does not need reconditioning. Its clean engine compartment is free of fluid leaks. It also has a clean title history, has complete and verifiable service records.

Fred Martin Motor Company - Tammy Carrico

CUSTOMER #:

712992



FRED MARTIN SUPERSTORE

INTERNAL

3195 Barber Road
Barberton, Ohio 44203-1011
(330) 753-4444
Fax (330) 753-2940
FCA 26453

PAGE 1

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 7481 TROY DITTEMORE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
GRAY	19	JEEP COMPASS	3C4NJCB8KT676592		66879/66882	261970

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			18:00 13MAY26		0.00	CASH	14MAY26

R.O. OPENED READY OPTIONS: STK:1C261970AV DLR:FMMC-S ENG:2.4_Liter

08:17 12MAY26 16:34 14MAY26

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A PREMIUM OIL AND FILTER CHANGE TOP OFF ALL FLUID LEVELS AND RESET TIRE PRESSURES

2600 PREMIUM OIL AND FILTER CHANGE TOP OFF ALL FLUID LEVELS AND RESET TIRE PRESSURES

8128	IUC	0.40				23.00	23.00
1	SM2222	OIL FILTER			6.27	6.27	6.27
6	SYNOW20	0W20 DEXOS SYN			9.00	9.00	54.00

66879 0.40 THE TECHNICIAN CHANGED THE ENGINE OIL AND OIL FILTER, LUBRICATED CHASSIS, SET TIRE PRESSURES AND TOPPED OFF FLUIDS

B RADIO IS BLACK

CAUSE: DUE TO COMPLEX INTERACTIONS OF MULTIPLE COMPUTERS, (MODULES) IT IS POSSIBLE FOR ONE DEFECT TO MASK AND OR BLOCK ADDITIONAL DEFECTS. BECAUSE OF THIS IT IS POSSIBLE TO PERFORM A VALID REPAIR ONLY FOR WARNING LIGHT TO ILLUMINATE AND AN ADDITIONAL DEFEC

810 TROUBLE SHOOT STEREO DISPLAY FOUND INTERNAL FAILURE

8128	IUC	1.00				120.00	120.00
1	Z8396668AF	RADIO			324.00	324.00	324.00

66879 1.00 inspected found radio to have a bad lcd screen

C INFO

INFO INFO

8128	IUC	0.00				0.00	0.00
2	2504BPP	BULB			51.76	38.80	77.60

D** found that the lcd screen was the cause of radio issues checked all other all ok

800 found that the lcd screen was the cause of radio issues checked all other all ok

8128	IUC	1.00				120.00	120.00
------	-----	------	--	--	--	--------	--------

66879 1.00 replaced reprogrammed radio

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."	DESCRIPTION	TOTALS
<p>Disclaimer of Warranties Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.</p> <p>NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.</p>	LABOR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES	
	TOTAL CHARGES	
	LESS INSURANCE	
	SALES TAX	
	PLEASE PAY THIS AMOUNT	

X

CUSTOMER #:

712992



FRED MARTIN SUPERSTORE

INTERNAL

3195 Barber Road
Barberton, Ohio 44203-1011
(330) 753-4444
Fax (330) 753-2940
FCA 26453

PAGE 2

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 7481 TROY DITTEMORE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
GRAY	19	JEEP COMPASS	3C4NJCB8KT676592		66879/66882	261970

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			18:00 13MAY26		0.00	CASH	14MAY26

R.O. OPENED	READY	OPTIONS:
08:17 12MAY26	16:34 14MAY26	STK:1C261970AV DLR:FMMC-S ENG:2.4_Liter

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

E** both front day time running lights out aw well as message on dash for them
 800 both front day time running lights out aw well as message on dash for them
 8128 IUC 1.20 144.00 144.00
 66879 1.20 removed replaced day time running lights

 ESTIMATE: 0.00 12MAY26 11:32 SA: 7481
 CONTACT:

SHOP SUPPLIES 20.00

SCHEDULE YOUR NEXT SERVICE ONLINE AT
 WWW.FREDMARTINSUPERSTORE.COM AND GET \$5.00
 OFF THAT VISIT

COST, SALE, & COMP TOTALS 44273 86887 0

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto." Disclaimer of Warranties Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.	DESCRIPTION	TOTALS
	LABOR AMOUNT	407.00
	PARTS AMOUNT	461.87
	GAS, OIL, LUBE	0.00
	SUBLET AMOUNT	0.00
	MISC. CHARGES	20.00
	TOTAL CHARGES	888.87
	LESS INSURANCE	0.00
	SALES TAX	0.00
	PLEASE PAY THIS AMOUNT	888.87

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

[Home](#) > [Jeep](#) > [Jeep Compass](#) > [2019 Jeep Compass](#)

Used 2019 Jeep Compass

3.6 ★ Expert 4.7 ★ Consumer [Write a Review](#)

[Save This Car](#)

Exterior (36)

Interior (49)



- 2026
- 2025
- 2024
- 2023
- 2022
- 2021
- 2020
- 2019
- 2018
- 2017
- 2016
- 2015
- 2014
- 2013
- 2012
- 2011
- >

Fuel Economy
25 combined mpg

Horsepower
180 hp

Seating
5

Cargo Volume
59.8 cu ft

Next Steps: Shopping for this car?

See Cars for Sale

Build & Price

[Get My Car's Value](#) →

Reviews Consumer Reviews Cars For Sale Values & Prices Depreciation Specs & Features Safety Compare

2019 Jeep Compass Review



By **Rob Nestora** ⓘ
Updated May 29, 2025

Pros

The 2019 Jeep Compass has a rugged look, an impressive array of features and the ability to go places a Nissan Rogue Sport or Kia Sportage can only dream about. The price is right, at least on entry-level trims, and you can still get a manual transmission on the Sport and 4WD Latitude trims.

Cons

The Jeep Compass isn't big on power, resale, fuel economy or stellar reliability ratings. If you need something with more room, the larger Cherokee or a Honda CR-V makes a better choice. Driver assists standard on some rivals are still optional on the Compass.

What's New?

For 2019, the Jeep Compass gets some new option packages, including the Upland package on the Sport trim that adds the Trailhawk's front bumper, tow hooks, front skidplate and all-weather mats. Sport and Latitude models gain a 7-inch Uconnect radio, while adaptive cruise control is added to the Advanced Safety Group package.

Slotting between the quirky Renegade and larger Cherokee, the 2019 Jeep Compass is a compact-crossover SUV that looks very much like a full-size Grand Cherokee that was left in the dryer a bit too long. With a starting price under \$23,000, the Compass offers an appealing reason to buy, as do its many unique features and options. As with all Jeeps, the Compass is a competent off-roader, especially in Trailhawk trim. The Compass' 4-cylinder engine isn't much on power or refinement, but it gets the job done. You'll find better fuel-economy numbers from the



[Read Full Review](#)

Advertisement

Advertisement

Advertisement

New Jeep Compass Deals and Incentives

APR

1.9% APR | 72 months

Get 1.9% for 72 months on a new 2026 COMPASS LIMITED ALTITUDE 4X4.

[See more details](#)

End Date: 06/01/2026

CASH

\$1750 Total Cash

Get up to \$1750 Cash Allowance on a new 2026 COMPASS LIMITED ALTITUDE 4X4.

[See more details](#)

End Date: 06/01/2026

[See All Current Compass Deals](#) →

2019 Jeep Compass KBB.com Consumer Reviews

4.7 Consumer Rating Based on 499 Consumer Reviews

[Write a Review](#)

93% Recommend this vehicle



[Read Consumer Reviews](#)

Used Cars

Cars You May Like

We've rounded up cars that could be your perfect match.

<p>Used 2019 Jeep Compass Latitude</p> <p>\$15,700 GOOD PRICE</p> <p>Reduced</p> <p>Fred Martin Superstore</p> <p>Confirm Availability </p>	<p>Used 2019 Jeep Compass Latitude w/ Popular Equipment Group</p> <p>\$17,500 GREAT PRICE</p> <p>Valley Chrysler Jeep Dodge Ram Of The Falls</p> <p>Confirm Availability </p>	<p>Used 2019 Jeep Compass Latitude w/ Popular Equipment Group</p> <p>\$17,800 GREAT PRICE</p> <p>Reduced</p> <p>Genesis of Mentor</p> <p>Confirm Availability </p>	<p>Used Jeep Ad</p> <p>\$1</p> <p>Reduced</p> <p>Driv</p> <p>Confirm Availability </p>
--	--	---	---

[Browse All Listings](#) →

2019 Jeep Compass Values and Prices

Style	Trade-In Value	Private Party Value	Fair Purchase Price
Sport SUV 4D	\$8,800	\$11,850	\$13,100
Upland Sport Utility 4D	\$9,100	\$11,800	\$13,050
High Altitude Sport Utility 4D	\$10,200	\$11,500	\$12,700
Latitude Sport Utility 4D	\$9,325	\$13,000	\$14,450
Altitude Sport Utility 4D	\$9,575	\$13,350	\$14,800
Limited Sport Utility 4D	\$9,775	\$13,850	\$15,250
Trailhawk Sport Utility 4D	\$10,350	\$14,050	\$15,500

Values above are based on "Good" condition vehicles [①](#). Estimated Trade-In Values range from about \$8,800 to \$10,350 depending on vehicle style. Estimated Private Party Values range from about \$11,500 to \$14,050 depending on vehicle style. Values and prices are based on national averages and typical mileage for this model, but they can vary greatly according to mileage, condition, location, and other factors. Valid through 5/18/2026.



Trade-In Value

Trade-In Value is the amount you can expect to receive this week when trading in your vehicle at a dealership.



Private Party Value

Private Party Value is the fair price you can expect when selling your car to an individual, not to a dealer.



Fair Purchase Price

Fair Purchase Price shows what others in your area are actually paying for this vehicle.

[See Full Specs for All 2019 Jeep Compass Styles](#) →

Advertisement

2019 Jeep Compass

Depreciation

A 2019 Jeep Compass has depreciated \$5,914 or 33% in the last 3 years and has a current resale value of \$11,850 and trade-in value of \$8,800.



Historical ———

Forecast - - - -

2019 Jeep Compass

View up to 3 vehicles to compare depreciation.

Add Vehicle

2019 Jeep Compass Annual Depreciation ⓘ

Year	Vehicle Depreciation*	Resale Value	Trade-In Value
2023	\$2,887	\$17,764	\$16,042
2024	\$3,278	\$14,486	\$12,840
2025	\$3,704	\$10,782	\$9,092
Now	+ \$1,068	\$11,850	\$8,800
2027	\$1,965	\$9,885	\$7,341
2028	\$2,061	\$7,824	\$5,810

*Depreciation for the last 12 months of the private party resale value.

2019 Jeep Compass Depreciation

Annual Depreciation is an estimation of what your vehicle's value might be over time based on an average of similar vehicles. Estimations are calculated by comparing Kelley Blue Book Private Party Values of vehicles similar to yours over time, as well as forecasts from Manheim Auction data comparing current and projected auction values against current Kelley Blue Book Private Party and Trade-In Values. This is not a guarantee of actual depreciation. Local weather conditions, market factors and driver performance will also impact your vehicle's actual depreciation.

Is this information helpful?



[Learn More About 2019 Jeep Compass Depreciation](#) →

Already Own This Car?

[Get My Car's Value](#) →

[See Cars for Sale](#)



Calculate Your Budget With These KBB.com Tools

[Car Financing 101](#) →

[Car Loan Calculator](#) →

[Car Lease Calculator](#) →

[Car Affordability Calculator](#) →

Specifications

Fuel Economy

City 22 mpg/Hwy 30 mpg/Comb 25 mpg

Fuel Type

Gas

Basic Warranty

3 years or 36000 miles

Max Seating

5

Horsepower

180 @ 6400 RPM

Cargo Space

59.8 cu.ft.

[Read More](#)

2019 Jeep Compass Safety

Safety Features & Technology

- Child Door Locks
- Child Seat Anchors
- Driver Airbag
- Passenger Airbag
- Stability Control
- Traction Control
- Driver Knee Airbag
- Front Head Curtain Airbag
- Front Side Airbag
- Rear Head Curtain Airbag
- Rear Parking Sensors
- Rear View Camera

4.0 Crash Test Rating

Provided by the National Highway Traffic Safety Administration

Frontal Crash	4.0	Side Barrier	5.0
Rollover Rating	3.0	Side Crash	5.0

Compare to Similar Vehicles



Used 2019
Jeep Compass



Used 2019
Nissan Rogue

[See Details](#)



Used 2019
Chevrolet Equinox

[See Details](#)



Used 2019
GMC Terrain

[See Details](#)

Price	\$13,100	\$16,600	\$13,000 ✓	\$15,050
KBB.com Rating	3.6	4.3	4.4	4.4
Consumer Rating	4.7 ✓	4.1	3.9	3.9
Fuel Economy	City 22/Hwy 30/Comb 25 MPG	City 31/Hwy 34/Comb 33 MPG ✓	City 26/Hwy 32/Comb 28 MPG	City 26/Hwy 30/Comb 28 MPG
Fuel Type	Gas	N/A	N/A	N/A
Safety Rating	4.0	4.0	5.0	5.0



Used 2019
Jeep Compass



Used 2019
Nissan Rogue

[See Details](#)



Used 2019
Chevrolet Equinox

[See Details](#)



Used 2019
GMC Terrain

[See Details](#)

Seating Capacity	5	5	5	5
-------------------------	---	---	---	---

2019 Jeep Compass Rankings

Horsepower **MPG Combined** **Consumer Ratings**

Rank	Vehicles	HP
#1	2019 Nissan Pathfinder	284
#2	2019 Ford Edge	250
#3	2019 Land Rover Discovery Sport	237
#4	2019 Hyundai Kona Electric	201
#10	2019 Jeep Compass	180

More Jeep Compass News & Information

Subcompact SUV Crossover

2025 Jeep Compass Stays Unchanged, Under \$30K

No one is ever sure whether the Jeep Compass is a compact or subcompact SUV, which makes it just the...

Sean Tucker | July 30, 2024

Compact SUV Crossover

Tests: Emergency Braking Struggles

Car safety technology keeps advancing. To keep pace, one of America's major car safety watchdogs keeps coming up with tougher...

Sean Tucker | April 25, 2024

Compact SUV Crossover

2024 Jeep Compass Starts Under \$28,000

The Jeep brand has been moving upmarket recently, offering 6-figure large SUVs and even Wrangler models pushing over the \$90,000...

FAQs

How much should a 2019 Jeep Compass cost?

Used 2019 Jeep Compass prices currently range from \$13,100 for the High Altitude Sport Utility 4D to \$15,500 for the Trailhawk Sport Utility 4D when purchasing from a dealership, depending on a range of factors like equipment, mileage, and condition.

What's the cheapest Jeep Compass?

The cheapest 2019 Jeep Compass is the High Altitude Sport Utility 4D, with a Kelley Blue Book Fair Purchase Price of \$13,100.

Is the 2019 Jeep Compass reliable?

The 2019 Jeep Compass is part of the 3rd-generation Compass, which our owners give an above-average reliability rating of 4.7 out of 5.

Also from Jeep

[2019 Jeep Cherokee](#)

[2019 Jeep Grand Cherokee](#)

[2019 Jeep Renegade](#)

[2019 Jeep Wrangler](#)

[2019 Jeep Wrangler Unlimited](#)

[FAQ](#) | [Contact Us](#) | [Privacy Notice](#) | [Do Not Sell or Share My Personal Information](#) | [Limit the Use of My Sensitive Personal Information](#)
| [Manage Cookies](#) | [About Us](#) | [Careers](#) | [Corporate](#) | [Marketing and Advertising Solutions](#) | [Media](#) | [Site Map](#) |
[KBB Brazil](#) | [KBB Canada](#)



Home / Vehicle ratings / [2019 Jeep Compass 4-door SUV](#)

2019 Jeep Compass

SMALL SUV / 4-DOOR SUV



2018 Jeep Compass shown

Crashworthiness

Small overlap front: driver-side	G
Small overlap front: passenger-side	G
Moderate overlap front: original test	G
Side: original test	G
Side: updated test	M
Roof strength	G
Head restraints & seats	G

Crash avoidance & mitigation

Headlights (varies by trim/option)	M P
Front crash prevention: vehicle-to-vehicle Optional system (built after December 2016)	
Front crash prevention: pedestrian (day)	NOT AVAILABLE

Seat belts & child restraints

LATCH ease of use	P
-------------------	----------

Other available safety features

- Optional blind spot detection

- Optional lane departure warning
- Optional lane departure prevention

Key

G Good	Superior
A Acceptable	Advanced
M Marginal	Basic
P Poor	

Some ratings use a scale of Poor to Good. Others range from Basic to Superior.

Small overlap front: driver-side

Tested vehicle: **2017 Jeep Compass Sport 4-door 4wd**
Rating applies to 2017-21 models built after December 2016

The Jeep Compass was redesigned during the 2017 model year. (A short run of old-design 2017 models was produced through December 2016.) All 2017 and later Compass models built after December 2016 are the redesigned vehicles. (Information about when a specific vehicle was manufactured is on the certification label typically affixed to the car on the driver door or adjacent B-pillar.)

Overall evaluation	G
Structure and safety cage	G
Driver injury measures	
Head/neck	G
Chest	G
Hip/thigh	G
Lower leg/foot	G
Driver restraints and dummy kinematics	G



Action shot taken during the driver-side small overlap frontal crash test.



The dummy's position in relation to the door frame, steering wheel, and instrument panel after the crash test indicates that the driver's survival space was maintained very well.



The frontal and side curtain airbags worked well together to keep the head from coming close to any stiff structure or outside objects that could cause injury.



The driver's space was maintained well, and risk of injuries to the dummy's legs and feet was low.

► Technical measurements for this test

Small overlap front: passenger-side

Tested vehicle: **2018 Jeep Compass Sport 4-door 4wd**

Rating applies to 2017-21 models built after December 2016

The Jeep Compass was redesigned during the 2017 model year. (A short run of old-design 2017 models was produced through December 2016.) All 2017 and later Compass models built after December 2016 are the redesigned vehicles. (Information about

when a specific vehicle was manufactured is on the certification label typically affixed to the car on the driver door or adjacent B-pillar.)

Overall evaluation	G
Structure and safety cage	A
Passenger injury measures	
Head/neck	G
Chest	G
Hip/thigh	G
Lower leg/foot	A
Passenger restraints and dummy kinematics	G
Driver injury measures	
Head/neck	G
Chest	G
Hip/thigh	G
Lower leg/foot	G
Driver restraints and dummy kinematics	G



Action shot taken during the passenger-side small overlap frontal crash test.



The dummy's position in relation to the door frame and dashboard after the crash test indicates that the passenger's survival space was maintained reasonably well.



The frontal and side curtain airbags worked well together to keep the passenger dummy's head from coming close to any stiff structure or outside objects that could cause injury.



Intrusion of the dashboard contributed to a moderate risk of injury to the right lower leg.

► Technical measurements for this test

Moderate overlap front: original test

Tested vehicle: **2017 Jeep Compass Latitude 4-door 4wd**

Rating applies to 2017-21 models built after December 2016

The Jeep Compass was redesigned during the 2017 model year. (A short run of old-design 2017 models was produced through December 2016.) All 2017 and later Compass models built after December 2016 are the redesigned vehicles. (Information about

when a specific vehicle was manufactured is on the certification label typically affixed to the car on the driver door or adjacent B-pillar.)

Moderate overlap frontal ratings are assigned by the Institute based on a test conducted by Fiat Chrysler.

Overall evaluation **G**

Structure and safety cage **G**

Driver injury measures

Head/neck **G**

Chest **G**

Leg/foot, left **G**

Leg/foot, right **G**

Driver restraints and dummy kinematics **G**

► Technical measurements for this test

Side: original test

Tested vehicle: **2017 Jeep Compass Latitude 4-door 4wd**

Rating applies to 2017-21 models built after December 2016

The Jeep Compass was redesigned during the 2017 model year. (A short run of old-design 2017 models was produced through December 2016.) All 2017 and later Compass models built after December 2016 are the redesigned vehicles. (Information about when a specific vehicle was manufactured is on the certification label typically affixed to the car on the driver door or adjacent B-pillar.)

Side ratings are assigned by the Institute based on a test conducted by Fiat Chrysler.

Overall evaluation **G**

Structure and safety cage **G**

Driver injury measures

Head/neck **G**

Torso **G**

Pelvis/leg **G**

Driver head protection **G**

Rear passenger injury measures

Head/neck	G
Torso	G
Pelvis/leg	G
Rear passenger head protection	G

► Technical measurements for this test

Side: updated test

Tested vehicle: **2021 Jeep Compass Latitude 4-door 4wd**

Rating applies to 2017-21 models built after December 2016

The Jeep Compass was redesigned during the 2017 model year. (A short run of old-design 2017 models was produced through December 2016.) All 2017 and later Compass models built after December 2016 are the redesigned vehicles. (Information about when a specific vehicle was manufactured is on the certification label typically affixed to the car on the driver door or adjacent B-pillar.)

Overall evaluation	M
Structure and safety cage	M
Driver injury measures	
Head/neck	G
Torso	A
Pelvis	P
Driver head protection	G
Rear passenger injury measures	
Head/neck	G
Torso	A
Pelvis	A
Rear passenger head protection	G



View of the vehicle just after the crash test.



View of the vehicle after the crash with doors removed, showing the side airbags and damage to the occupant compartment.



Smearred greasepaint shows where the driver dummy's head was protected from being hit by hard structures by the side airbags.



Smeared greasepaint shows where the rear passenger dummy's head was protected by the side airbag.

► Technical measurements for this test

Roof strength

Tested vehicle: **2017 Jeep Compass Latitude 4-door 4wd**

Rating applies to 2017-23 models built after December 2016

Overall evaluation

G

Curb weight	3,429 lbs
Peak force	16,952 lbs
Strength-to-weight ratio	4.94

Head restraints & seats

Seat type: **Manual leatherette seat**

Overall evaluation	G
Dynamic rating	G
Seat/head restraint geometry	G

► Technical measurements for this test


Headlights

Ratings are given for **3 different headlight variations** available on this vehicle.

(1) Trim level(s): Latitude trim equipped with Premium Lighting Group and Advanced Safety Group packages, Trailhawk trim equipped with Premium Lighting Group and Advanced Safety Group packages, Limited trim equipped with Premium Lighting Group and Advanced Safety Group packages

Low-beam headlight type	HID projector
High-beam headlight type	HID projector
Curve-adaptive?	No
High-beam assist?	Yes
Overall rating	M

Distance at which headlights provide at least 5 lux illumination:



Low beams

On the straightaway, visibility was fair on the left side of the road and inadequate on the right side. On curves, visibility was good on the gradual right curve, fair on the sharp right and sharp left curves, and inadequate on the gradual left curve.

The low beams never exceeded glare limits.

High beams

On the straightaway, visibility was inadequate on both sides of the road. On curves, visibility was fair on the gradual right and gradual left curves and inadequate on the sharp right and sharp left curves.

► Technical measurements for this test

(3) Trim level(s): Sport trim, Latitude trim, Trailhawk trim, Limited trim

Low-beam headlight type Halogen reflector


High-beam headlight type Halogen reflector

Curve-adaptive? No

High-beam assist? No

Overall rating **P**

Distance at which headlights provide at least 5 lux illumination:



Low beams

On the straightaway, visibility was fair on the right side of the road and inadequate on the left side. On curves, visibility was inadequate in all 4 tests.

The low beams never exceeded glare limits.

High beams

On the straightaway, visibility was good on the right side of the road and inadequate on the left side. On curves, visibility was inadequate in all 4 tests.

► Technical measurements for this test

Front crash prevention: vehicle-to-vehicle

System details

- optional Full Speed Forward Collision Warning Plus

Package name

- optional Advanced Safety Group

Overall evaluation

SUPERIOR
WITH
OPTIONAL
EQUIPMENT

Applies to 2017-21 models built after December 2016


- This system meets the requirements for forward collision warning.
- In the 12 mph test, this vehicle avoided a collision.
- In the 25 mph test, this vehicle avoided a collision.

Child seat anchors

Rating applies to 2017-19 models built after December 2016

Overall evaluation	P
Vehicle trim	Latitude
Seat type	leatherette

This vehicle has 2 rear seating positions with complete child seat attachment (LATCH) hardware. It has 1 additional seating position with a tether anchor only.



Details by seating position

- 1 Tether anchor**
 - easy-to-find location
 - no other hardware could be confused for anchor
- Lower anchors**
 - too deep in seat
 - too much force needed to attach
 - difficult to maneuver around anchors
- 2 Tether anchor**
 - easy-to-find location
 - no other hardware could be confused for anchor
- Lower anchors**
 - none available
- 3 Tether anchor**

- G** Good
- A** Acceptable
- M** Marginal
- P** Poor
- Seating positions that rely on borrowed lower anchors or have only a tether anchor available

are not rated.

Tether anchor

Lower anchors

Lower anchor(s) can be borrowed from adjacent positions(s)

■ No hardware available

easy-to-find location

no other hardware could be confused for anchor

Lower anchors

too deep in seat

too much force needed to attach

difficult to maneuver around anchors

► Technical measurements for this test



Vehicle ratings

News

Research areas

Who we are

Member groups

Careers

Media resources

Contact us

A free resource for students and teachers [↗](#)

Learn about the initiative

Making roads and vehicles safer for everyone.

The **Insurance Institute for Highway Safety (IIHS)** is an independent, nonprofit scientific and educational organization dedicated to reducing deaths, injuries and property damage from motor vehicle crashes through research and evaluation and through education of consumers, policymakers and safety professionals.

The **Highway Loss Data Institute (HLDI)** shares and supports this mission through scientific studies of insurance data representing the human and economic losses resulting from the ownership and operation of different types of vehicles and by publishing insurance loss results by vehicle make and model.

Both organizations are wholly supported by [these auto insurers and insurance associations](#).

©1996-2026, Insurance Institute for Highway Safety, Highway Loss Data Institute, 501(c)(3) organizations | [Copyright information and privacy policy](#).