

WE HAVE TRIED OUR BEST TO ENSURE THE ACCURACY OF THE INFORMATION LISTED BELOW, BUT MISTAKES DO HAPPEN. PRIOR TO PURCHASE, BUYER SHOULD VERIFY ALL THE OPTIONS LISTED BELOW TO BE ACCURATE. WE MAKE NO REPRESENTATION TO THE ACCURACY OF THIS INFORMATION.

FRED MARTIN SUPERSTORE

AutoCheck
BUYBACK
Protection

Request an AutoCheck®
Vehicle History Report To See
The Detailed History On Any Car,
Truck, Van or SUV In Seconds!

fredmartinsuperstore.com

**FINANCING
AVAILABLE!†**



**LIFETIME LIMITED
POWERTRAIN WARRANTY***

*SOME RESTRICTIONS APPLY SEE BELOW.

**ALL
TRADE-INS
WELCOME!**

2016 Honda HR-V EX-L w/Navigation AWD

Odometer: 80,629
Engine: 1.8L I4 SOHC 16V i-VTEC
Color: Modern Steel Metallic
Interior: Black w/Leather Seat Trim

Transmission: CVT
VIN: 3CZRU6H77GM723507
Stock #: 1C263087AV
Drivetrain: AWD

COMFORT EQUIPMENT AND ACCESSORIES

Safety

4-Wheel Disc Brakes
ABS brakes
Dual front impact airbags
Dual front side impact airbags
Front anti-roll bar
Front wheel independent suspension
Low tire pressure warning
Occupant sensing airbag
Overhead airbag
Rear anti-roll bar
Brake assist

Additional

ONE OWNER!
ALL-WHEEL DRIVE
NAVIGATION
POWER SUNROOF
17" ALLOY WHEELS
BLUETOOTH PHONE AND AUDIO
HEATED FRONT BUCKET SEATS
LEATHER-TRIMMED INTERIOR
LANEWATCH RIGHT SIDE CAMERA

Exterior

Power moonroof
Front fog lights
Fully automatic headlights
Bumpers: body-color
Heated door mirrors
Power door mirrors
Roof rack: rails only
Spoiler
Turn signal indicator mirrors
17" Alloy Wheels
Alloy wheels

Electronic

Honda Satellite-Linked Navigation System
Navigation System
6 Speakers
AM/FM radio: SiriusXM
CD player
Radio data system
Radio: AM/FM/CD/HD/SiriusXM Audio System

Technical

Traction control

Interior

Air Conditioning
Automatic temperature control
Rear window defroster
Power steering
Power windows
Remote keyless entry
Steering wheel mounted audio controls
Speed control
Auto-dimming Rear-View mirror
Driver door bin



GET PRE-QUALIFIED NOW!

THIS WILL NOT IMPACT OR EFFECT YOUR CREDIT SCORE!

For More Information, Check Out This Vehicle Online



NO-CHARGE EXTRAS!*



**3 YEARS OF FREE
OIL CHANGES**



**15 DAY
LOVE IT OR LEAVE IT
RETURN GUARANTEE**



**3 YEARS OF FREE
ROADSIDE ASSISTANCE**



**FREE AUTOCHECK®
VEHICLE HISTORY REPORT
WITH BUYBACK PROTECTION**



**NO LEMON
GUARANTEE**

IT IS THE RESPONSIBILITY OF THE PURCHASER TO VERIFY THE OPTIONS LISTED ON THIS LABEL ARE CORRECT PRIOR TO BUYING THIS VEHICLE. ALTHOUGH WE HAVE USED A COMPUTER SCREENING PROCESS TO ENSURE THE ACCURACY OF THIS LABEL THE PURCHASER MUST VERIFY THE EQUIPMENT LISTED ON THIS LABEL IS ACTUALLY ON THE VEHICLE, AS MISTAKES DO OCCUR. THE NO CHARGE ITEMS LISTED ABOVE AND AN * (ASTERISK) APPLY TO SELECT VEHICLES WITH A FINAL SELLING PRICE OF \$12,000.00 OR ABOVE BEFORE TAX, TITLE, AND DOCUMENTARY FEE. EACH OF THE ITEMS LISTED WITH AN * (ASTERISK) HAVE A WRITTEN DOCUMENT DETAILING THEIR BENEFITS AND SHOULD BE READ AND UNDERSTOOD BY THE PURCHASER PRIOR TO PURCHASING THIS VEHICLE. † WITH APPROVED CREDIT.

Experian AutoCheck Report

Report run: 08/05/2026 10:00:45 EDT

This report is brought to you by:
Fred Martin Superstore **ELITE MEMBER**
3195 Barber Rd Norton, OH 44203
330.753.4444

2016 Honda HR-V EX-L w/Navi

SUV 4D (1.8L I4 SMPI Gasoline)

VIN:	3CZRU6H77GM723507
Class:	CUV - Compact
Country of Assembly:	Mexico
Vehicle Age:	10 year(s)
Estimated In Service:	11/19/2015
Last Reported Odometer:	80,628 (07/28/2026)



Vehicle Usage
Personal



AutoCheck Score
Similar vehicles usually range between **67** and **80**

Vehicle History at a Glance

 State Title Brand CLEAN	 Auction Brand / Issues NO ISSUE	 Accident / Damage No Accidents or Damage Reported NO ISSUE
 Open Recall Check NO OPEN RECALLS	 Insurance Loss / Transfer NO ISSUE	 Odometer Check Last reported odometer: 80,628 (07/28/2026) NO ISSUE
 Certified Pre-Owned NO CPO INFO AVAILABLE	 Service / Repair 27 Service Record(s) Reported NO ISSUE	 Additional History Lien Reported, Inspection Performed EVENTS REPORTED



This vehicle is AutoCheck Assured™
This vehicle does not have any state title brands or other major problems reported.


[Learn More](#)



Accident & Damage

Your Vehicle Checks Out

There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.



Airbag Deployed



Structural Damage



Overturned



No Damage



Inspection History Check



Information Reported

Below are inspection(s) that were reported for this vehicle. Please note that not all inspections are reported to Experian AutoCheck.

Inspection Date - 06/14/2019

Location - CORTLANDT MANOR, NY

Odometer Reading -

Data Source - Independent Source

Details - Independent Inspection/Theft Deterrent Equipped



Service History

Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.



Regular Oil Changes

- 4 oil services reported
- Last oil service reported 06/16/2026



Fluids Maintained

Information not available.



Brakes Maintained

- 2 brake pad replacements
- Brake last maintained on 09/15/2017



Tires Maintained

Information not available.



A/C & Climate Control

Information not available.



Other Services

- Cabin air filter replaced on 06/16/2026

OEM Recommended Services



80000 Mile Service

- Adjust parking brake (if applicable)
- Adjust Tire Pressure
- Alignment



85000 Mile Service Not Yet Due

- Adjust parking brake (if applicable)
- Adjust Tire Pressure
- Alignment



Odometer Check



Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported



Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2016 Honda HR-V EX-L w/Navi (3CZRU6H77GM723507) Report Run Date: 08/05/2026 10:00:45 EDT

2015

Owner 1

Location: NYOwned From: 11/2015Usage: Personal				
Event Date	Location	Odometer	Data Source	Details
11/19/2015	CORTLANDT MANOR, NY		Motor Vehicle Dept.	Registration Event/Renewal
12/14/2015	PEEKSKILL, NY	4	Motor Vehicle Dept.	Title(Lien Reported)
12/14/2015	PEEKSKILL, NY		Motor Vehicle Dept.	Title(Lien Reported)
07/08/2017	YORKTOWN HEIGHTS, NY	10,071	Service Record	Multiple Point Vehicle Inspection
07/08/2017	YORKTOWN HEIGHTS, NY		Service Record	Engine Serviced Brakes Serviced Drive Line Serviced Suspension Serviced Tires or Wheels Service Performed
07/15/2017	YORKTOWN HEIGHTS, NY	10,247	Service Record	Multiple Point Vehicle Inspection
07/15/2017	YORKTOWN HEIGHTS, NY		Service Record	Engine Serviced Chassis Serviced Brakes Serviced Drive Line Serviced Suspension Serviced Tires or Wheels Service Performed
09/12/2017	YORKTOWN HEIGHTS, NY	11,882	Service Record	Multiple Point Vehicle Inspection
09/12/2017	YORKTOWN HEIGHTS, NY		Service Record	Brakes Serviced Suspension Serviced Tires or Wheels Service Performed
09/15/2017	YORKTOWN HEIGHTS, NY	11,932	Service Record	Multiple Point Vehicle Inspection
09/15/2017	YORKTOWN HEIGHTS, NY		Service Record	Chassis Serviced Brakes Serviced Suspension Serviced Tires or Wheels Service Performed
10/11/2017	CORTLANDT MANOR, NY		Motor Vehicle Dept.	Registration Event/Renewal
11/03/2017	YORKTOWN HEIGHTS, NY	12,856	Service Record	Fuel System Serviced
11/03/2017	YORKTOWN HEIGHTS, NY		Service Record	Multiple Point Vehicle Inspection Engine Serviced Transmission Serviced Drive Line Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
11/06/2018	YORKTOWN HEIGHTS, NY	19,969	Service Record	Fuel System Serviced
11/06/2018	YORKTOWN HEIGHTS, NY		Service Record	Multiple Point Vehicle Inspection Engine Serviced Recommended Maintenance Performed Wipers Replaced And/Or Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
06/14/2019	CORTLANDT MANOR, NY		Independent Source	Independent Inspection/Theft Deterrent Equipped
09/06/2019	YORKTOWN HEIGHTS, NY	26,433	Service Record	Fuel System Serviced

Event Date	Location	Odometer	Data Source	Details
09/06/2019	NY		Service Record	Vehicle Inspected
09/06/2019	YORKTOWN HEIGHTS, NY		Service Record	Multiple Point Vehicle Inspection Engine Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
09/06/2019	NY		Service Record	Promotional Service Performed
10/01/2019	PEEKSKILL, NY		Motor Vehicle Dept.	Registration Event/Renewal
11/06/2019	NY	27,744	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection
11/17/2020	NY	33,611	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection
12/09/2020			Manufacturer	Manufacturer Service Bulletin Mfr. Recall V92 Warranty Extension: 2016-18 HR-V START SWITCH WARRANTY EXTENSION LOCATE YOUR NEAREST AUTHORIZED HONDA DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
04/27/2021			Manufacturer	Manufacturer Service Bulletin Mfr. Recall JAT Warranty Extension: 2016-20 HR-V CVT BELT DETERIORATION WARRANTY EXTENSION LOCATE YOUR NEAREST AUTHORIZED HONDA DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
08/31/2021	PEEKSKILL, NY		Motor Vehicle Dept.	Registration Event/Renewal
11/16/2021	NY	40,581	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection
04/11/2022	NY	43,507	Service Record	Vehicle Inspected
04/11/2022	YORKTOWN HEIGHTS, NY		Service Record	Multiple Point Vehicle Inspection
04/11/2022	NY		Service Record	Vehicle Recall Service Performed
04/11/2022	YORKTOWN HEIGHTS, NY		Service Record	Engine Serviced
04/11/2022	NY		Service Record	Recommended Maintenance Performed
04/11/2022	YORKTOWN HEIGHTS, NY		Service Record	Transmission Serviced
04/11/2022	NY		Service Record	Engine Serviced Electrical System Serviced
04/11/2022	YORKTOWN HEIGHTS, NY		Service Record	Tires or Wheels Service Performed
04/11/2022	NY		Service Record	Promotional Service Performed
11/09/2022	NY	49,038	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection
10/17/2023	PEEKSKILL, NY		Motor Vehicle Dept.	Registration Event/Renewal
11/17/2023	NY	56,795	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection
11/19/2024	NY	65,950	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection
09/29/2025	PEEKSKILL, NY		Motor Vehicle Dept.	Registration Event/Renewal
06/16/2026	ONLINE DEALER	80,525	Dealer Listing	Vehicle Listed for Sale
06/16/2026	YORKTOWN HEIGHTS, NY	80,525	Service Record	Air Filter Changed Multiple Point Vehicle Inspection Engine Serviced Wipers Replaced And/Or Serviced Transmission Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
06/23/2026	NY		Service Record	Vehicle Inspected Lights or Signals Serviced
07/28/2026	ONLINE DEALER	80,628	Dealer Listing	Vehicle Listed for Sale



Warranty Check

To see your estimated warranty coverage details, please enter a mileage reading below. The warranty coverage shown is an estimate using the best available in-service date, the mileage reading you enter, and warranty information. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to **AutoCheck Terms and Conditions**. If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.

Here is a list of some major defects that may occur in used vehicles.

Frame & Body

Frame-cracks, corrective welds, or rusted through
Dog tracks—bent or twisted frame

Engine

Oil leakage, excluding normal seepage
Cracked block or head
Belts missing or inoperable
Knocks or misses related to camshaft lifters and push rods
Abnormal exhaust discharge

Transmission & Drive Shaft

Improper fluid level or leakage, excluding normal seepage
Cracked or damaged case which is visible
Abnormal noise or vibration caused by faulty transmission or drive shaft
Improper shifting or functioning in any gear
Manual clutch slips or chatters

Differential

Improper fluid level or leakage, excluding normal seepage
Cracked or damaged housing which is visible
Abnormal noise or vibration caused by faulty differential

Cooling System

Leakage including radiator
Improperly functioning water pump

Electrical System

Battery leakage
Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories

Gauges or warning devices
Air conditioner
Heater & Defroster

Brake System

Failure warning light broken
Pedal not firm under pressure (DOT spec.)
Not enough pedal reserve (DOT spec.)
Does not stop vehicle in straight line (DOT spec.)
Hoses damaged
Drum or rotor too thin (Mfr. Specs)
Lining or pad thickness less than 1/32 inch
Power unit not operating or leaking
Structural or mechanical parts damaged

Air Bags

Steering System

Too much free play at steering wheel (DOT specs.)
Free play in linkage more than 1/4 inch
Steering gear binds or jams
Front wheels aligned improperly (DOT specs.)
Power unit belts cracked or slipping
Power unit fluid level improper

Suspension System

Ball joint seals damaged
Structural parts bent or damaged
Stabilizer bar disconnected
Spring broken
Shock absorber mounting loose
Rubber bushings damaged or missing
Radius rod damaged or missing
Shock absorber leaking or functioning improperly

Tires

Tread depth less than 2/32 inch
Sizes mismatched
Visible damage

Wheels

Visible cracks, damage or repairs
Mounting bolts loose or missing

Exhaust System

Leakage
Catalytic Converter

Fred Martin Motor Company

DEALER NAME

3195 Barber Rd, Barberton, Ohio 44203

ADDRESS

(330) 753-4444

TELEPHONE

EMAIL

Sales Manager

FOR COMPLAINTS AFTER SALE, CONTACT:

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).

Trade In/Loan/Retail Breakdown

J.D. Power

Publication 08/2026, Region: Central

2016 HONDA HR-V Utility 4D EX-L Navigation AWD 1.8L I4 Auto \$11,400 / \$10,275 / \$12,075

VIN: 3CZRU6H77GM723507

Stock #: 1C263087AV

MSRP	25990
Weight	3109
Condition	Clean
Total Value without mileage	\$11,400 / \$10,275 / \$12,075
Mileage adjustment (80629) miles	\$3,025

*** J.D. Power Trade In/Loan/Retail
\$14,425 / \$13,300 / \$15,100

Fred Martin Motor Company - Rebecca Mowery

J.D. Power publication for Ohio: Publication 08/2026, Region: Central

Values are subjective opinions. J.D. Power and vAuto, Inc. assume no responsibility for errors or omissions.

© vAuto, Inc. 2026, all rights reserved.

Typical Listing Price/Trade In/Private Party/Fair Purchase Price Breakdown

KBB.com

08/05/2026 Edition 44203

2016 Honda HR-V EX-L Sport Utility 4D \$15,930 / \$11,300 / \$15,050 / \$15,290

VIN: 3CZRU6H77GM723507

Stock #: 1C263087AV

*** Itemized Add/Deducts ***

4-Cyl, i-VTEC, 1.8 Liter	Included	AM/FM Stereo	Included
Auto, CVT w/Sport Mode	Included	CD/MP3 (Single Disc)	Included
AWD	Included	SiriusXM Satellite	Included
LaneWatch	Included	Navigation System	Included
Hill Start Assist Control	Included	Bluetooth Wireless	Included
Traction Control	Included	HondaLink	Included
Stability Control	Included	Backup Camera	Included
ABS (4-Wheel)	Included	Dual Air Bags	Included
Anti-Theft System	Included	Side Air Bags	Included
Keyless Entry	Included	F&R Head Curtain Air Bags	Included
Keyless Start	Included	Heated Seats	Included
Air Conditioning	Included	Leather	Included
Power Windows	Included	Moon Roof	Included
Power Door Locks	Included	Daytime Running Lights	Included
Cruise Control	Included	Fog Lights	Included
Power Steering	Included	Rear Spoiler	Included
Tilt & Telescoping Wheel	Included	Alloy Wheels	Included

Condition Excellent*

Total Value without mileage \$15,930 / \$11,300 / \$15,050 / \$15,290

Mileage adjustment (80629) miles \$1,660

***** KBB.com Typical Listing Price/Trade In/Private Party/Fair Purchase Price
\$17,590 / \$12,960 / \$16,710 / \$16,950**

"Excellent" - 3% of all cars we value meet this criteria. This car looks new and is in excellent mechanical condition. It has never had paint or bodywork and has an interior and body free of wear and visible defects. The car is rust-free and does not need reconditioning. Its clean engine compartment is free of fluid leaks. It also has a clean title history, has complete and verifiable service records.

Fred Martin Motor Company - Rebecca Mowery

the specification, mileage and/or condition information provided by the person generating this report. Kelley Blue Book assume no responsibility for errors or omissions.

© vAuto, Inc. 2026, all rights reserved.

[Home](#) > [Honda](#) > [Honda HR-V](#) > 2016 Honda HR-V

#3 Best 2-Row SUVs of 2016

Used 2016 Honda HR-V

4.7 ★ Expert 4.1 ★ Consumer [Write a Review](#)

[Save This Car](#)

Exterior (31)

Interior (39)



- 2027
- 2026
- 2025
- 2024
- 2023
- 2022
- 2021
- 2020
- 2019
- 2018
- 2017



Fuel Economy

29 - 31 combined mpg

Horsepower

141 hp

Seating

5

Cargo Volume

55.9 - 58.8 cu ft

Next Steps: Shopping for this car?

See Cars for Sale

Build & Price

[Get My Car's Value](#) →

- Reviews
- Consumer Reviews
- Cars For Sale
- Values & Prices
- Depreciation
- Specs & Featu

2016 Honda HR-V Review



By **Matt Degen** ⓘ

Updated December 23, 2019

Pros

If you've been craving a smaller Honda that splits the difference between the Fit and CR-V, you'll find it in the HR-V. The HR-V also has a value-conscious price that starts under \$20,000, yet it offers an interior and features that feel more premium than what's found in the Fit.

Cons

The new HR-V doesn't have as much zippy appeal as the Mazda CX-3 or Fiat 500X, or the off-road chops of the Jeep Renegade. Only one engine is available. If you need a small SUV that can tow, check out the Renegade or a larger SUV like Honda's own CR-V.

What's New?

The 2016 Honda HR-V is a brand-new crossover SUV. Sized between the Fit and CR-V, it uses a 4-cylinder engine that achieves up to 35 mpg and is offered with a manual transmission or automatic continuously variable transmission (CVT).


The 2016 Honda HR-V is a brand-new vehicle that slots between the CR-V compact SUV and the smaller Fit hatchback, melding the best traits of each. With its taller profile and available all-wheel



[Read Full Review](#)

Advertisement

Advertisement



Advertisement

New Honda HR-V Deals and Incentives

APR

3.99% APR | 48 months

Get 3.99% APR 24-48 MOS. or 4.99% APR 49-60 MOS. or 5.99% APR 61-72 MOS. for well-qualified buyers on a new 2027 HR-V.

[See more details](#)

End Date: 09/08/2026

LEASE

\$249 /mo | 36 months | Due at Signing

Closed end lease for a new 2027 HR-V LX 2WD Continuously Variable Transmission for \$249 a month for 36 months with \$3599 due at signing for well-qualified lessees.

[See more details](#)

End Date: 09/08/2026

[See All Current HR-V Deals →](#)

2016 Honda HR-V

KBB.com Consumer Reviews

4.1 Consumer Rating [Based on 142 Consumer Reviews](#)

[Write a Review](#)

70% Recommend this vehicle

5 ★	52%
4 ★	23%
3 ★	13%
2 ★	5%



[Read Consumer Reviews](#)

Used Cars

Cars You May Like

We've rounded up cars that could be your perfect match.

Used 2016 Honda HR-V EX-L	Used 2016 Honda HR-V EX-L	Used 2016 Honda HR-V EX-L
-------------------------------------	-------------------------------------	-------------------------------------

\$15,995  GREAT PRICE

New Listing

New Line Motors, Inc.

Confirm Availability 

\$19,045  GOOD PRICE

Germain Honda of Dublin

Confirm Availability 

\$13

Byers

[Browse All Listings](#) →

2016 Honda HR-V Values and Prices

Style	Trade-In Value	Private Party Value	Fair Purchase Price
LX Sport Utility 4D	\$8,275	\$11,700	\$12,850
EX Sport Utility 4D	\$9,575	\$12,450	\$13,700
EX-L Sport Utility 4D	\$10,550	\$14,100	\$15,500

Values above are based on "Good" condition vehicles ⓘ. Estimated Trade-In Values range from about \$8,275 to \$10,550 depending on vehicle style. Estimated Private Party Values range from about \$11,700 to \$14,100 depending on vehicle style. Values and prices are based on national averages and typical mileage for this model, but they can vary greatly according to mileage, condition, location, and other factors. Valid through 8/5/2026.



Trade-In Value

Trade-In Value is the amount you can expect to receive this week when trading in your vehicle at a dealership.



Private Party Value

Private Party Value is the fair price you can expect when selling your car to an individual, not to a dealer.



Fair Purchase Price

Fair Purchase Price shows what others in your area are actually paying for this vehicle.

[See Full Specs for All 2016 Honda HR-V Styles](#) →

Advertisement

2016 Honda HR-V

Depreciation

A 2016 Honda HR-V has a current resale value of \$11,700 and trade-in value of \$8,275. [i](#)

Login or create a new account to see your vehicle depreciation forecast data.

Historical 

Forecast 

2016 Honda HR-V

Compare up to 3 vehicles by logging in.

[Log In / Sign Up](#)

2016 Honda HR-V Annual Depreciation ⓘ

Year	Vehicle Depreciation*	Resale Value	Trade-In Value
2023	\$2,359	\$11,399	\$10,265
2024	\$1,580	\$9,819	\$8,719
2025	\$1,461	\$8,358	\$7,094
Now	+ \$3,342	\$11,700	\$8,275

[Unlock
Forecast](#)[2-Year
Forecasted
Depreciation](#)

*Depreciation for the last 12 months of the private party resale value.

2016 Honda HR-V Depreciation

Annual Depreciation is an estimation of what your vehicle's value might be over time based on an average of similar vehicles. Estimations are calculated by comparing Kelley Blue Book Private Party Values of vehicles similar to yours over time, as well as forecasts from Manheim Auction data comparing current and projected auction values against current Kelley Blue Book Private Party and Trade-In Values. This is not a guarantee of actual depreciation. Local weather conditions, market factors and driver performance will also impact your vehicle's actual depreciation.

Is this information helpful?



[Learn More About 2016 Honda HR-V
Depreciation](#)



Already Own This Car?

[Get My Car's Value](#) →

[See Cars for Sale](#)



Calculate Your Budget With These KBB.com Tools

[Car Financing 101](#) →

[Car Loan Calculator](#) →

[Car Lease Calculator](#) →

[Car Affordability Calculator](#) →

Specifications

Fuel Economy

City 28 mpg/Hwy 35 mpg/Comb 31 mpg

Fuel Type

Gas

Basic Warranty

Max Seating

8/5/26, 10:05 AM	2016 Honda HR-V Price, Value, Depreciation & Reviews Kelley Blue Book
3 years or 36000 miles	5
Horsepower 141 @ 6500 RPM	Cargo Space 58.8 cu.ft.
Read More	

2016 Honda HR-V Safety

Safety Features & Technology

- Child Door Locks
- Child Seat Anchors
- Driver Airbag
- Passenger Airbag
- Stability Control
- Traction Control
- Front Head Curtain Airbag
- Front Side Airbag
- Rear Head Curtain Airbag
- Rear View Camera

5.0

Crash Test Rating

Provided by the National Highway Traffic Safety Administration

Frontal Crash	4.0	Side Barrier	5.0
Rollover Rating		Side Crash	

4.0

5.0

Compare to Similar Vehicles



Used 2016
Honda HR-V



Used 2020
Hyundai Venue

[See Details](#)


Used 2020
Chevrolet Trax

[See Details](#)


Used 2017
Kia Sportage

[See Details](#)

Price	\$12,850	\$12,450	\$11,650 ✓	\$11,700
KBB.com Rating	4.7 ✓	4.5	3.9	4.5
Consumer Rating	4.1	4.5 ✓	3.4	4.4
Fuel Economy	City 28/Hwy 35/Comb 31 MPG	City 30/Hwy 34/Comb 32 MPG ✓	City 26/Hwy 31/Comb 28 MPG	City 20/Hwy 23/Comb 21 MPG
Fuel Type	Gas	Gas	Gas	Gas
Safety Rating	5.0	N/A	5.0	5.0
Seating Capacity	5	5	5	5
Basic Warranty	3 years or 36000 miles	5 years or 60000 miles	3 years or 36000 miles	5 years or 60000 miles
Horsepower	141 @ 6500 RPM	121 @ 6300 RPM	138 @ 4900 RPM	241 @ 6000 RPM ✓
Engine	4-Cyl, i-VTEC, 1.8 Liter	4-Cyl, 1.6 Liter	4-Cyl, ECOTEC, Turbo, 1.4 Liter	4-Cyl, Turbo, GDI, 2.0L



2016 Honda HR-V Rankings

Horsepower **MPG Combined** **Consumer Ratings**

Rank	Vehicles	HP
#1	2017 Nissan Armada	390
#2	2018 Lincoln MKT	365
#3	2017 Ford Flex	365
#4	2016 Ford Expedition EL	365
#61	2016 Honda HR-V	141

More Honda HR-V News & Information

Subcompact SUV Crossover

Our 3 Favorite Things About the 2026 Honda HR-V

Here are a few of our favorite things about the 2026 Honda HR-V, one of America's best-selling subcompact SUVs.

Jasmine Bingham | August 04, 2026

Subcompact SUV Crossover

Let's Take a Look Inside the 2024 Honda HR-V

The 2024 Honda HR-V is a subcompact SUV with a reputation for value, good fuel economy, and agility. After a...

Nick Kurczewski | September 26, 2023

Subcompact SUV Crossover

This Is the Most Popular 2024 Honda HR-V

The 2024 Honda HR-V is a subcompact SUV that doesn't feel like one. It escapes many of the drawbacks common...

Sean Tucker | June 01, 2023

FAQs

Is the 2016 Honda HR-V a good vehicle?

Yes, the 2016 Honda HR-V is a good car, as reflected by its above-average Kelley Blue Book rating of 4.7 out of 5.

What is the MPG for a 2016 Honda HR-V?

2016 Honda HR-V city/highway fuel economy ratings range from 27/32 mpg to 28/35 mpg, depending on trim and equipment.

How much should a 2016 Honda HR-V cost?

Used 2016 Honda HR-V prices currently range from \$12,850 for the LX Sport Utility 4D to \$15,500 for the EX-L Sport Utility 4D when purchasing from a dealership, depending on a range of factors like equipment, mileage, and condition.

What's the cheapest Honda HR-V?

The cheapest 2016 Honda HR-V is the LX Sport Utility 4D, with a Kelley Blue Book Fair Purchase Price of \$12,850.

Is the 2016 Honda HR-V reliable?

The 2016 Honda HR-V is part of the 1st-generation HR-V, which our owners give an above-average reliability rating of 4.4 out of 5.

Also from Honda

2016 Honda Accord

2016 Honda CR-V

2016 Honda CR-Z

2016 Honda Civic

2016 Honda Fit

2016 Honda Odyssey

2016 Honda Pilot

[FAQ](#) | [Contact Us](#) | [Privacy Notice](#) | [Do Not Sell or Share My Personal Information](#) | [Limit the Use of My Sensitive Personal Information](#) | [Manage Cookies](#) | [About Us](#) | [Careers](#) | [Corporate](#) | [Marketing and Advertising Solutions](#) | [Media](#) | [Site Map](#) | [KBB Brazil](#) |

KBB Canada

Kelley Blue Book, a Cox Automotive Company

© 1995-2026 Kelley Blue Book Co.®, Inc. All rights reserved.

[Copyrights & Trademarks](#) | [Vehicle Photos © Evox Images](#) | [Terms of Service](#) | [Linking Policy](#) | [Accessibility Statement](#)



Home / Vehicle ratings / 2016 Honda HR-V 4-door SUV

2016 Honda HR-V

SMALL SUV / 4-DOOR SUV



Crashworthiness

Small overlap front: driver-side	A
Moderate overlap front: original test	G
Side: original test	A
Roof strength	G
Head restraints & seats	G

Crash avoidance & mitigation

Headlights	P
Front crash prevention: vehicle-to-vehicle	NOT AVAILABLE

Seat belts & child restraints

LATCH ease of use	M
-------------------	---

Key

G	Good	Superior
A	Acceptable	Advanced
M	Marginal	Basic
P	Poor	

Some ratings use a scale of Poor to Good. Others range from Basic to Superior.

Small overlap front: driver-side

Tested vehicle: **2016 Honda HR-V LX 4-door 4wd**

Rating applies to 2016-18 models

The Honda HR-V was introduced in the 2016 model year.

Overall evaluation	A
Structure and safety cage	A
Driver injury measures	
Head/neck	G
Chest	G
Hip/thigh	G
Lower leg/foot	G

Driver restraints and dummy kinematics

The dummy’s head contacted the frontal airbag but moved too far to the left side, leaving the head vulnerable to contact with forward structure. Additionally, the seat belt allowed excessive forward excursion of the dummy’s head and torso. The side curtain airbag deployed and has sufficient forward coverage to protect the head from contact with side structure and outside objects. The side torso airbag also deployed.

A



Action shot taken during the small overlap frontal crash test.



The dummy's position in relation to the door frame, steering wheel, and instrument panel after the crash test indicates that the driver's survival space was maintained reasonably well.



The seat belt allowed too much forward movement of the dummy to the extent that its head approached the intruding A-pillar.



The driver's space was maintained reasonably well, and risk of injuries to the dummy's legs and feet was low.

► Technical measurements for this test

Moderate overlap front: original test

Tested vehicle: **2016 Honda HR-V EX 4-door 4wd**

Rating applies to 2016-18 models

The Honda HR-V was introduced in the 2016 model year.

Overall evaluation	G
Structure and safety cage	G
Driver injury measures	
Head/neck	G
Chest	G
Leg/foot, left	G
Leg/foot, right	G
Driver restraints and dummy kinematics	G



Action shot taken during the moderate overlap frontal crash test.



The dummy's position in relation to the steering wheel and instrument panel after the crash test indicates that the driver's survival space was maintained very well.



Smeared greasepaint shows where the driver dummy's head was protected from hitting hard structures during rebound by the side curtain airbag.



Intrusion into the driver's space was minimal, and all leg and foot injury measures were low.

► Technical measurements for this test

Side: original test

Tested vehicle: **2016 Honda HR-V EX 4-door 4wd**

Rating applies to 2016-17 models built before April 2017

The Honda HR-V was introduced in the 2016 model year.

Overall evaluation	A
Structure and safety cage	P
Driver injury measures	
Head/neck	G
Torso	G
Pelvis/leg	M
Driver head protection	G
Rear passenger injury measures	
Head/neck	G
Torso	G
Pelvis/leg	G
Rear passenger head protection	G




View of the 2016 Honda HR-V and barrier just after the crash test.



View of the vehicle after the crash with doors removed, showing the side airbags and damage to the occupant compartment. The lower B-pillar was torn away from the door sills, contributing to greatly increased structural intrusion.



Smeared greasepaint shows where the driver dummy's head was protected from being hit by hard structures by the side curtain airbag.



Smeared greasepaint shows where the rear passenger dummy's head was protected by the side airbag.

► Technical measurements for this test

Roof strength

Tested vehicle: **2016 Honda HR-V LX 4-door 4wd**

Rating applies to 2016-22 models

Overall evaluation

G

Curb weight	3,035 lbs
Peak force	15,604 lbs
Strength-to-weight ratio	5.14

Head restraints & seats

Seat type: Manual cloth seat

Overall evaluation	G
Dynamic rating	G
Seat/head restraint geometry	G


► Technical measurements for this test

Headlights

Trim level(s): All trims

Low-beam headlight type	Halogen reflector
High-beam headlight type	Halogen reflector
Curve-adaptive?	No
High-beam assist?	No
Overall rating	P

Distance at which headlights provide at least 5 lux illumination:



Low beams

On the straightaway, visibility was inadequate on both sides of the road. On curves, visibility was inadequate in all 4 tests. The low beams never exceeded glare limits.

High beams

On the straightaway, visibility was inadequate on both sides of the road. On curves, visibility was inadequate in all 4 tests.

► Technical measurements for this test

Child seat anchors


Ratings are given for 2 different child seat anchor configurations available on this vehicle.

(1) Child seat anchor configuration

Rating applies to 2016-18 models

Overall evaluation	M
Vehicle trim	EX
Seat type	cloth

This vehicle has 2 rear seating positions with complete child seat attachment (LATCH) hardware. It has 1 additional seating position with a tether anchor only.



- G

Good
- A

Acceptable
- M

Marginal
- P

Poor
- ☐

Seating positions that rely on borrowed lower anchors or have only a tether anchor available are not rated.

Tether anchor

Lower anchors

Lower anchor(s) can be borrowed from adjacent position(s)
- ☐

No hardware available

Details by seating position

- 1

Tether anchor

easy-to-find location

other hardware could be confused for anchor

Lower anchors

too deep in seat

too much force needed to attach

easy to maneuver around anchors
- 2

Tether anchor

hard-to-find location

no other hardware could be confused for anchor

Lower anchors

none available
- 3

Tether anchor

easy-to-find location

other hardware could be confused for anchor

Lower anchors

too deep in seat

too much force needed to attach


easy to maneuver around anchors

► Technical measurements for this test

(2) Child seat anchor configuration

Rating applies to 2016-18 models

Overall evaluation	M
Vehicle trim	LX
Seat type	cloth



- G

Good
- A

Acceptable
- M

Marginal
- P

Poor
- ☐

Seating positions that rely on borrowed lower anchors or have only a tether anchor available are not rated.

Tether anchor

Lower anchors

Lower anchor(s) can be borrowed from adjacent position(s)
- ☐

No hardware available

Details by seating position

- 1

Tether anchor

easy-to-find location

other hardware could be confused for anchor

Lower anchors

too deep in seat

too much force needed to attach

easy to maneuver around anchors
- 2

Tether anchor

hard-to-find location

no other hardware could be confused for anchor

Lower anchors

none available
- 3

Tether anchor

easy-to-find location

other hardware could be confused for anchor

Lower anchors

too deep in seat

too much force needed to attach

easy to maneuver around anchors

► Technical measurements for this test



[Vehicle ratings](#)[News](#)[Research areas](#)[Who we are](#)[Member groups](#)[Careers](#)[Media resources](#)[Contact us](#)

A free resource for students and teachers [↗](#)

[Learn about the initiative](#)

Making roads and vehicles safer for everyone.

The **Insurance Institute for Highway Safety (IIHS)** is an independent, nonprofit scientific and educational organization dedicated to reducing deaths, injuries and property damage from motor vehicle crashes through research and evaluation and through education of consumers, policymakers and safety professionals.

The **Highway Loss Data Institute (HLDI)** shares and supports this mission through scientific studies of insurance data representing the human and economic losses resulting from the ownership and operation of different types of vehicles and by publishing insurance loss results by vehicle make and model.

Both organizations are wholly supported by [these auto insurers and insurance associations](#).

©1996-2026, Insurance Institute for Highway Safety, Highway Loss Data Institute, 501(c)(3) organizations | [Copyright information and privacy policy](#).