

WE HAVE TRIED OUR BEST TO ENSURE THE ACCURACY OF THE INFORMATION LISTED BELOW, BUT MISTAKES DO HAPPEN. PRIOR TO PURCHASE, BUYER SHOULD VERIFY ALL THE OPTIONS LISTED BELOW TO BE ACCURATE. WE MAKE NO REPRESENTATION TO THE ACCURACY OF THIS INFORMATION.

FRED MARTIN SUPERSTORE

AutoCheck
BUYBACK
Protection

Request an AutoCheck®
Vehicle History Report To See
The Detailed History On Any Car,
Truck, Van or SUV In Seconds!

fredmartinsuperstore.com



**LIFETIME LIMITED
POWERTRAIN WARRANTY***

*SOME RESTRICTIONS APPLY SEE BELOW.

**FINANCING
AVAILABLE!†**

**ALL
TRADE-INS
WELCOME!**

2018 Chevrolet Equinox LT

Odometer: 75,580
Engine: 1.5L DOHC
Color: Storm Blue Metallic
Interior: Jet Black Cloth

Transmission: 6-Speed Automatic Electronic with
Overdrive
VIN: 3GNAXJEV0JS599008
Stock #: 1C263224AP
Drivetrain: FWD

COMFORT EQUIPMENT AND ACCESSORIES

Safety

4-Wheel Disc Brakes
ABS brakes
Dual front impact airbags
Dual front side impact airbags
Emergency communication system:
OnStar and Chevrolet connected services
capable
Front anti-roll bar
Low tire pressure warning
Occupant sensing airbag
Overhead airbag
Rear anti-roll bar

Additional

APPLE CARPLAY & ANDROID AUTO
CITY MPG: 26 HIGHWAY MPG: 32
17" ALLOY WHEELS
BLUETOOTH PHONE & AUDIO
STABILITRAK STABILITY CONTROL
TEEN DRIVER MODE
REMOTE KEYLESS ENTRY
PUSH-BUTTON START

Exterior

Delay-off headlights
Fully automatic headlights
High-Intensity Discharge Headlights
Black Bowtie Emblems (LPO)
Bumpers: body-color
Heated door mirrors
Power door mirrors
Spoiler
17" Aluminum Wheels
Alloy wheels

Electronic

6 Speaker Audio System Feature
6 Speakers
AM/FM radio: SiriusXM
Premium audio system: Chevrolet MyLink
Radio data system
Radio: Chevrolet MyLink AM/FM Stereo
SiriusXM Satellite Radio
USB Port & Auxiliary Input Jack

Technical

Four wheel independent suspension
Speed-sensing steering
Traction control

Interior

Air Conditioning
Rear window defroster
8-Way Power Driver Seat Adjuster
Bluetooth® For Phone
Power driver seat
Power steering
Power windows
Remote keyless entry
Steering wheel mounted audio controls
Speed control



GET PRE-QUALIFIED NOW!

THIS WILL NOT IMPACT OR EFFECT YOUR CREDIT SCORE!

For More Information, Check Out This Vehicle Online



NO-CHARGE EXTRAS!*



**3 YEARS OF FREE
OIL CHANGES**



**15 DAY
LOVE IT OR LEAVE IT
RETURN GUARANTEE**



**3 YEARS OF FREE
ROADSIDE ASSISTANCE**



**FREE AUTOCHECK®
VEHICLE HISTORY REPORT
WITH BUYBACK PROTECTION†**



**NO LEMON
GUARANTEE**

IT IS THE RESPONSIBILITY OF THE PURCHASER TO VERIFY THE OPTIONS LISTED ON THIS LABEL ARE CORRECT PRIOR TO BUYING THIS VEHICLE. ALTHOUGH WE HAVE USED A COMPUTER SCREENING PROCESS TO ENSURE THE ACCURACY OF THIS LABEL THE PURCHASER MUST VERIFY THE EQUIPMENT LISTED ON THIS LABEL IS ACTUALLY ON THE VEHICLE, AS MISTAKES DO OCCUR. THE NO CHARGE ITEMS LISTED ABOVE AND AN * (ASTERISK) APPLY TO SELECT VEHICLES WITH A FINAL SELLING PRICE OF \$12,000.00 OR ABOVE BEFORE TAX, TITLE, AND DOCUMENTARY FEE. EACH OF THE ITEMS LISTED WITH AN * (ASTERISK) HAVE A WRITTEN DOCUMENT DETAILING THEIR BENEFITS AND SHOULD BE READ AND UNDERSTOOD BY THE PURCHASER PRIOR TO PURCHASING THIS VEHICLE. † WITH APPROVED CREDIT.

Experian AutoCheck Report

Report run: 09/22/2026 15:10:12 EDT

This report is brought to you by:
Fred Martin Superstore **ELITE MEMBER**
3195 Barber Rd Norton, OH 44203
330.753.4444

2018 Chevrolet Equinox LT

SUV 4D (1.5L I4 DI Gasoline)

VIN:	3GNAXJEV0JS599008
Class:	CUV - Midsize
Country of Assembly:	Mexico
Vehicle Age:	8 year(s)
Estimated In Service:	03/09/2018
Last Reported Odometer:	75,580 (09/05/2026)



Vehicle Usage
Personal



AutoCheck Score
Similar vehicles usually range between **87** and **92**

Vehicle History at a Glance

 State Title Brand CLEAN	 Auction Brand / Issues NO ISSUE	 Accident / Damage DAMAGE REPORTED
 Open Recall Check NO OPEN RECALLS	 Insurance Loss / Transfer NO ISSUE	 Odometer Check Last reported odometer: 75,580 (09/05/2026) NO ISSUE
 Certified Pre-Owned NO CPO INFO AVAILABLE	 Service / Repair 9 Service Record(s) Reported NO ISSUE	 Additional History Lien Reported EVENTS REPORTED



This vehicle is AutoCheck Assured™
This vehicle does not have any state title brands or other major problems reported.

Learn More



Accident & Damage

Airbag Deployed

Structural Damage

Overturned

Unknown

Damage Date	Damage Type	Severity
01/19/2025	Collision	Unknown
Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.		



Service History

Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.



Regular Oil Changes

- 1 oil services reported
- Last oil service reported 09/02/2026



Fluids Maintained

- 1 coolant flushes
- Last fluid maintained 09/02/2026



Brakes Maintained

- 1 brake pad replacements
- Brake last maintained on 09/02/2026



Tires Maintained

Information not available.



A/C & Climate Control

Information not available.



Other Services

Information not available.

OEM Recommended Services



75000 Mile Service

- Change engine oil and filter
- Check accelerator pedal
- Check engine coolant and washer fluid



82500 Mile Service Not Yet Due

- Change engine oil and filter
- Check accelerator pedal
- Check engine coolant and washer fluid



Odometer Check



Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported



Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.
Vehicle: 2018 Chevrolet Equinox LT (3GNAXJEV0JS599008) Report Run Date: 09/22/2026 15:10:12 EDT

2018

Owner 1

Location: NJ

Owned From: 03/2018

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
03/09/2018	CLIFTON, NJ	18	Motor Vehicle Dept.	Title
04/06/2018	CLIFTON, NJ		Motor Vehicle Dept.	Registration Event/Renewal
03/03/2022	CLIFTON, NJ		Motor Vehicle Dept.	Registration Event/Renewal
02/06/2023	CLIFTON, NJ		Motor Vehicle Dept.	Registration Event/Renewal
03/09/2023	LODI, NJ	43,929	Motor Vehicle Dept.	Passed Emission Inspection
02/03/2024	CLIFTON, NJ		Motor Vehicle Dept.	Registration Event/Renewal
01/19/2025	WALLINGTON, NJ		Police Report	Accident Reported(Report #:25-000887)
03/03/2025	CLIFTON, NJ		Motor Vehicle Dept.	Registration Event/Renewal
03/03/2025	PARAMUS, NJ	61,824	Motor Vehicle Dept.	Passed Emission Inspection
04/03/2026	CLIFTON, NJ		Motor Vehicle Dept.	Registration Event/Renewal
05/23/2026	ONLINE DEALER	75,528	Dealer Listing	Vehicle Listed for Sale
05/28/2026	CLIFTON, NJ	75,528	Motor Vehicle Dept.	Title
06/02/2026	NJ	75,528	Service Record	Vehicle Serviced or Inspected
06/03/2026	NJ	75,529	Service Record	Vehicle Serviced or Inspected
06/09/2026	NJ		Service Record	Vehicle Serviced or Inspected
06/23/2026	NJ		Service Record	Vehicle Inspected Tires or Wheels Service Performed
06/25/2026	PA	75,567	Auto Auction	Reported at Auto Auction
06/29/2026	PA	75,567	Auto Auction	Reported at Auto Auction as Dealer Vehicle
08/03/2026	PA	75,568	Auto Auction	Reported at Auto Auction as Dealer Vehicle(COLOR REPORTED AS BLUE)
08/07/2026	PA	75,568	Auto Auction	Reported at Auto Auction
08/10/2026	ONLINE DEALER	75,568	Dealer Listing	Vehicle Listed for Sale
08/14/2026	BARBERTON, OH	75,575 †	Dealer Listing	Vehicle Listed for Sale
08/21/2026	BARBERTON, OH	75,568	Motor Vehicle Dept.	Title(Lien Reported)
08/24/2026	OH	75,575	Service Record	Vehicle Detailed
09/02/2026	OH		Service Record	Vehicle Inspected Brakes Serviced Electrical System Serviced Lights or Signals Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Vehicle Fluids Serviced
09/03/2026	OH	75,578	Service Record	Vehicle Detailed
09/04/2026	OH		Service Record	Vehicle Detailed
09/05/2026	OH	75,580	Service Record	Vehicle Detailed

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

Warranty Check

To see your estimated warranty coverage details, please enter a mileage reading below. The warranty coverage shown is an estimate using the best available in-service date, the mileage reading you enter, and warranty information. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.

Here is a list of some major defects that may occur in used vehicles.

Frame & Body

Frame-cracks, corrective welds, or rusted through
Dog tracks—bent or twisted frame

Engine

Oil leakage, excluding normal seepage
Cracked block or head
Belts missing or inoperable
Knocks or misses related to camshaft lifters and push rods
Abnormal exhaust discharge

Transmission & Drive Shaft

Improper fluid level or leakage, excluding normal seepage
Cracked or damaged case which is visible
Abnormal noise or vibration caused by faulty transmission or drive shaft
Improper shifting or functioning in any gear
Manual clutch slips or chatters

Differential

Improper fluid level or leakage, excluding normal seepage
Cracked or damaged housing which is visible
Abnormal noise or vibration caused by faulty differential

Cooling System

Leakage including radiator
Improperly functioning water pump

Electrical System

Battery leakage
Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories

Gauges or warning devices
Air conditioner
Heater & Defroster

Brake System

Failure warning light broken
Pedal not firm under pressure (DOT spec.)
Not enough pedal reserve (DOT spec.)
Does not stop vehicle in straight line (DOT spec.)
Hoses damaged
Drum or rotor too thin (Mfr. Specs)
Lining or pad thickness less than 1/32 inch
Power unit not operating or leaking
Structural or mechanical parts damaged

Air Bags

Steering System

Too much free play at steering wheel (DOT specs.)
Free play in linkage more than 1/4 inch
Steering gear binds or jams
Front wheels aligned improperly (DOT specs.)
Power unit belts cracked or slipping
Power unit fluid level improper

Suspension System

Ball joint seals damaged
Structural parts bent or damaged
Stabilizer bar disconnected
Spring broken
Shock absorber mounting loose
Rubber bushings damaged or missing
Radius rod damaged or missing
Shock absorber leaking or functioning improperly

Tires

Tread depth less than 2/32 inch
Sizes mismatched
Visible damage

Wheels

Visible cracks, damage or repairs
Mounting bolts loose or missing

Exhaust System

Leakage
Catalytic Converter

Fred Martin Motor Company

DEALER NAME

3195 Barber Rd, Barberton, Ohio 44203

ADDRESS

(330) 753-4444

TELEPHONE

EMAIL

Sales Manager

FOR COMPLAINTS AFTER SALE, CONTACT:

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).

Trade In/Loan/Retail Breakdown

J.D. Power

Publication 09/2026, Region: Central

2018 CHEVROLET TRUCKS Equinox Utility 4D LT 1.5L I4 Turbo \$8,725 / \$7,875 / \$10,250

VIN: 3GNAXJEV0JS599008

Stock #: 1C263224AP

MSRP 26800

Weight 3325

*** Itemized Add/Deducts ***

W/out Blind Spot Monitor -50 / -50 / -50

W/out Heated Front Seats -175 / -175 / -200

W/out Rear Parking Sensors -50 / -50 / -50

W/out Power Liftgate -100 / -100 / -125

W/out Remote Engine Starter -50 / -50 / -50

W/out Universal Garage Door Opener -25 / -25 / -25

Condition Clean

Total Value without mileage \$8,275 / \$7,425 / \$9,750

Mileage adjustment (75580) miles \$2,700

*** J.D. Power Trade In/Loan/Retail

\$10,975 / \$10,125 / \$12,450

Fred Martin Motor Company - Rebecca Mowery

J.D. Power publication for Ohio: Publication 09/2026, Region: Central

Values are subjective opinions. J.D. Power and vAuto, Inc. assume no responsibility for errors or omissions.

© vAuto, Inc. 2026, all rights reserved.

Typical Listing Price/Trade In/Private Party/Fair Purchase Price Breakdown

KBB.com

09/22/2026 Edition 44203

2018 Chevrolet Equinox LT Sport Utility 4D \$11,990 / \$8,035 / \$11,030 / \$11,220

VIN: 3GNAXJEV0JS599008

Stock #: 1C263224AP

*** Itemized Add/Deducts ***

4-Cyl, Turbo, 1.5 Liter	Included	Power Steering	Included
Automatic, 6-Spd w/Overdrive	Included	Tilt & Telescoping Wheel	Included
FWD	Included	AM/FM Radio w/MyLink	Included
Rollover Protection	Included	SiriusXM Satellite	Included
Hill Start Assist	Included	Bluetooth Wireless	Included
Traction Control	Included	OnStar	Included
StabiliTrak	Included	Backup Camera	Included
ABS (4-Wheel)	Included	Dual Air Bags	Included
Alarm System	Included	Side Air Bags	Included
Keyless Entry	Included	F&R Head Curtain Air Bags	Included
Keyless Start	Included	Power Seat	Included
Air Conditioning	Included	HID Headlamps	Included
Power Windows	Included	Daytime Running Lights	Included
Power Door Locks	Included	Alloy Wheels	Included
Cruise Control	Included		
Condition			Excellent*
Total Value without mileage			\$11,990 / \$8,035 / \$11,030 / \$11,220
Mileage adjustment (75580) miles			\$1,770

*** KBB.com Typical Listing Price/Trade In/Private Party/Fair Purchase Price
\$13,760 / \$9,805 / \$12,800 / \$12,990

*"Excellent" - 3% of all cars we value meet this criteria. This car looks new and is in excellent mechanical condition. It has never had paint or bodywork and has an interior and body free of wear and visible defects. The car is rust-free and does not need reconditioning. Its clean engine compartment is free of fluid leaks. It also has a clean title history, has complete and verifiable service records.

Fred Martin Motor Company - Rebecca Mowery

©2026 Kelley Blue Book Co, Inc. All rights reserved. As of 9/22/2026 Edition for 44203. Values and pricing are the opinion of Kelley Blue Book, and the actual price of a vehicle may vary. The value and pricing information displayed for a particular vehicle is based upon the specification, mileage and/or condition information provided by the person generating this report. Kelley Blue Book assume no responsibility for errors or omissions.

CUSTOMER #:

723610

INTERNAL

PAGE 1



FRED MARTIN SUPERSTORE

3195 Barber Road
Barberton, Ohio 44203-1011
(330) 753-4444
Fax (330) 753-2940
FCA 26453

HOME: CONT:N/A

BUS: CELL:

SERVICE ADVISOR: 7481 TROY DITTEMORE

SERVICE ADVISOR: 718-281-2222								
COLOR	YEAR	MAKE/MODEL		VIN		LICENSE	ODOMETER IN/ OUT	TAG
BLUE.	18	CHEVROLET EQUINOX		3GNAXJEV0JS599008			75575/75578	63224A
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE
DD			18:00 20AUG26			0.00	CASH	02SEP26

R.O. OPENED READY OPTIONS: STK:1C263224AP DLR:FMMC-S
ENG:1.5_Liter_DOHC_Turbo

14:34 17AUG26 12:51 02SEP26

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A PREMIUM OIL AND FILTER CHANGE TOP OFF ALL FLUID LEVELS AND RESET TIRE PRESSURES

2600 PREMIUM OIL AND FILTER CHANGE TOP OFF ALL FLUID LEVELS AND RESET TIRE PRESSURES

7572 IUC 0.40

28.00 28.00

1 PF64 OIL FILTER

9.95 9.95 9.95

5 SYN0W20 0W20 DEXOS SYN

9.00 9.00 45.00

1 WWS W/SOLVENT

1.75 1.57 1.57

1 COOLANT ANTIFREEZE

24.95 8.46 8.46

1 84151432 SENSOR

333.37 315.04 315.04

1 85761014 PIGTAIL

101.34 95.77 95.77

75575 .4 THE TECHNICIAN CHANGED THE ENGINE OIL AND OIL FILTER, LUBRICATED CHASSIS, SET TIRE PRESSURES AND TOPPED OFF FLUIDS

B Vehicle Inspection

SAF Vehicle Inspection

7572 IUC 1.00

120.00 120.00

3 1BP00260AA SENSOR-TIRE PRESSURE

59.81 59.81 179.43

1 QX1915 REAR PADS

75.00 75.00 75.00

2 SB581999 REAR ROTOR

75.00 75.00 150.00

1 LKQ USED MIRROR

143.57 135.68 135.68

1 85134219 BATTERY SENSOR

167.15 157.95 157.95

1 19333025 PIGTAIL

83.30 78.72 78.72

1 EBAY CONNECTER

30.00 30.00 30.00

EBAY397733195429

75575 1.0 INSPECTION COMPLETE

C INFO

INFO INFO

7572 IUC 0.00

0.00 0.00

D** CEL

CAUSE: DUE TO COMPLEX INTERACTIONS OF MULTIPLE COMPUTERS, (MODULES) IT IS POSSIBLE FOR ONE DEFECT TO MASK AND OR BLOCK ADDITIONAL

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

Disclaimer of Warranties Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #:

723610

INTERNAL

PAGE 2



FRED MARTIN SUPERSTORE

3195 Barber Road
Barberton, Ohio 44203-1011
(330) 753-4444
Fax (330) 753-2940
FCA 26453

HOME: CONT:N/A

BUS: CELL:

SERVICE ADVISOR: 7481 TROY DITTEMORE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
BLUE.	18	CHEVROLET EQUINOX	3GNAXJEV0JS599008		75575/75578	63224A	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			18:00 20AUG26		0.00	CASH	02SEP26

R.O. OPENED	READY	OPTIONS:
14:34 17AUG26	12:51 02SEP26	STK:1C263224AP DLR:FMMC-S ENG:1.5_Liter_DOHC_Turbo

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

DEFECTS. BECAUSE OF THIS IT IS POSSIBLE TO PERFORM A VALID
REPAIR ONLY FOR WARNING LIGHT TO ILLUMINATE AND AN ADDITIONAL
DEFEC

DIAG ENGINE PERFORMANCE DIAGNOSTICS

7572 IUC 1.00

120.00 120.00

75575 1.0 CEL ON FOR DTC U01B0 BATTERY SENSOR MODULE CIRCUIT.

INSPECTED AND FOUND BOTH WIRES BROKEN AT CONNECTOR END. REPAIR-REPLACE
CEL

E** AIRBAG LIGHT IS ON

CAUSE: DUE TO COMPLEX INTERACTIONS OF MULTIPLE COMPUTERS, (MODULES) IT
IS POSSIBLE FOR ONE DEFECT TO MASK AND OR BLOCK ADDITIONAL
DEFECTS. BECAUSE OF THIS IT IS POSSIBLE TO PERFORM A VALID
REPAIR ONLY FOR WARNING LIGHT TO ILLUMINATE AND AN ADDITIONAL
DEFEC

DIAG ENGINE PERFORMANCE DIAGNOSTICS

7572 IUC 1.00

120.00 120.00

75575 1.0 VERIFIED AIRBAG LIGHT ON FOUND DTC B0083 05 FOR LF IMPACT

SENSOR. INSPECTED AND FOUND WIRES BROKEN AT CONNECTOR END.
REPLACE-REPAIR AIRBAG LIGHT IS ON

F** TPMS LIGHT FLASHING

CAUSE: DUE TO COMPLEX INTERACTIONS OF MULTIPLE COMPUTERS, (MODULES) IT
IS POSSIBLE FOR ONE DEFECT TO MASK AND OR BLOCK ADDITIONAL
DEFECTS. BECAUSE OF THIS IT IS POSSIBLE TO PERFORM A VALID
REPAIR ONLY FOR WARNING LIGHT TO ILLUMINATE AND AN ADDITIONAL
DEFEC

DIAG ENGINE PERFORMANCE DIAGNOSTICS

7572 IUC 1.00

120.00 120.00

75575 1.0 DIAG TPMS NOT READING. FOUND ONLY RF SENSOR WORKING AT

THIS TIME. REPLACE LF LR RR TPMS LIGHT FLASHING

G** 2.0 REPLACE REAR PADS AND ROTORS. USE SCAN TOOL RETRACT REA

RBN REAR BRAKE PAD AND ROTOR REPLACEMENT

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

Disclaimer of Warranties Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

CUSTOMER #:

723610

INTERNAL

PAGE 3



FRED MARTIN SUPERSTORE

3195 Barber Road
Barberton, Ohio 44203-1011
(330) 753-4444
Fax (330) 753-2940
FCA 26453

HOME: CONT:N/A

BUS: CELL:

SERVICE ADVISOR: 7481 TROY DITTEMORE

SERVICE ADVISOR: 718-281-2222							
COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT	TAG
BLUE.	18	CHEVROLET EQUINOX		3GNAXJEV0JS599008		75575/75578	63224A
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			18:00 20AUG26		0.00	CASH	02SEP26

R.O. OPENED	READY	OPTIONS:
14:34 17AUG26	12:51 02SEP26	STK:1C263224AP DLR:FMMC-S ENG:1.5_Liter_DOHC_Turbo

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
				7572 IUC 2.00		240.00	240.00
	75575	2.0	REPLACED REAR PADS AND ROTORS				

H**	2.0	REPAIR DRIVER HEADLAMP CONNECTOR					
	800	2.0	REPAIR DRIVER HEADLAMP CONNECTOR				
			7572 IUC 2.00			240.00	240.00
	75575	2.0	REPLACE DRIVER FRONT HEADLAMP CONNECTOR. ALL OK AT THIS TIME.				

I**	1.0	DIAG DRIVER HEADLAMP INOP					
CAUSE: DUE TO COMPLEX INTERACTIONS OF MULTIPLE COMPUTERS, (MODULES) IT IS POSSIBLE FOR ONE DEFECT TO MASK AND OR BLOCK ADDITIONAL DEFECTS. BECAUSE OF THIS IT IS POSSIBLE TO PERFORM A VALID REPAIR ONLY FOR WARNING LIGHT TO ILLUMINATE AND AN ADDITIONAL DEFEC							
		DIAG ENGINE PERFORMANCE DIAGNOSTICS					
		7572 IUC 1.00				120.00	120.00
	75575	1.0	DIAG DRIVER HEADLAMP INOP. FOUND WIRES BROKEN AT CONNECTOR END. REPLACE-REPAIR				

J**	1.5	REPLACE DRIVER SIDE MIRROR ASSEMBLY. GLASS CRACKED HOUSING DAMAGED. NEED PAINTED					
	800	1.5	REPLACE DRIVER SIDE MIRROR ASSEMBLY. GLASS CRACKED HOUSING DAMAGED. NEED PAINTED				
			7572 IUC 1.50			180.00	180.00
	75575	1.5	REPLACE DRIVER REARVIEW MIRROR				

K		WALK AROUND VIDEO					
	800	WALK AROUND VIDEO					
			7572 IUC 0.00			0.00	0.00

L		MISC BODY DAMAGE					
	800	MISC BODY DAMAGE					
			7572 IUC 0.00			0.00	0.00

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

Disclaimer of Warranties Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

CUSTOMER #:

723610

INTERNAL

PAGE 4



FRED MARTIN SUPERSTORE

3195 Barber Road
Barberton, Ohio 44203-1011
(330) 753-4444
Fax (330) 753-2940
FCA 26453

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 7481 TROY DITTEMORE

SERVICE ADVISOR: 718-283-2222							
COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT	TAG
BLUE.	18	CHEVROLET EQUINOX		3GNAXJEV0JS599008		75575/75578	63224A
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			18:00 20AUG26		0.00	CASH	02SEP26

R.O. OPENED READY OPTIONS: STK:1C263224AP DLR:FMMC-S
ENG:1.5_Liter_DOHC_Turbo

14:34 17AUG26 12:51 02SEP26

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

M TURN FRONT ROTORS

TFR TURN FRONT ROTORS

7572 IUC 2.10

252.00 252.00

75575 2.1 RESRUFACE FRONT ROTORS

N** : 1.0 REPLACE BATTERY SENSOR MODULE CONNECTOR END

800 MISCELLANEOUS MECHANICAL

7572 IUC 1.00

120.00 120.00

75575 1.0 REPLACED BATTERY SENSOR MODULE CONNECTOR

O** 1.0 REPLACE LEFT FRONT IMPACT SENSOR CONNECTOR END

800 MISCELLANEOUS MECHANICAL

7572 IUC 1.00

120.00 120.00

75575 1.0 REPLACE CONNECTOR FOR FRONT IMPACT SENSOR

P** Tire Pressure Control Sensor: 1.8 X3 TIRE PRESSURE SENSORS

800 MISCELLANEOUS MECHANICAL

7572 IUC 1.80

216.00 216.00

75575 1.8 REPLACED X3 TIRE PRESSURE SENSORS

ESTIMATE: 0.00 19AUG26 12:05 SA: 7481

CONTACT:

SHOP SUPPLIES

20.00

SCHEDULE YOUR NEXT SERVICE ONLINE AT
WWW.FREDMARTINSUPERSTORE.COM AND GET \$5.00
OFF THAT VISIT

COST, SALE, & COMP TOTALS 173223 327857 0

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

Disclaimer of Warranties Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

DESCRIPTION	TOTALS
LABOR AMOUNT	1996.00
PARTS AMOUNT	1282.57
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	20.00
TOTAL CHARGES	3298.57
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	3298.57



[Home](#) > [Chevrolet](#) > [Chevrolet Equinox](#) > 2018 Chevrolet Equinox

#10 Best 2-Row SUVs of 2018

Used 2018 Chevrolet Equinox

4.4 ★ Expert 3.9 ★ Consumer [Write a Review](#)

♥ Save This Car

Exterior (44)



Interior (46)



Fuel Economy
28 combined mpg

Horsepower
170 hp

Seating
5

Cargo Volume
63.5 cu ft

Next Steps: Shopping for this car?

See Cars for Sale

Build & Price

Get My Car's Value →

- Reviews
- Consumer Reviews
- Cars For Sale
- Values & Prices
- Depreciation
- Specs & Features
- Safety
- Compare

2018 Chevrolet Equinox Review



By **Keith Buglewicz** ⓘ

Updated May 16, 2025

Pros

If you're a Chevy loyalist in the market for a compact crossover SUV, then you've found your ride. Even those new to the brand should take a look though, as the Equinox is a good-looking, nice-driving, and nicely featured compact SUV. Let's not forget the fuel-smart diesel and more powerful 4-cylinder.

Cons

If you demand the highest-tech safety features at the lowest possible price, then the fact that the new Equinox saves its active safety for the top-line Premier model may turn you off. Road trippers will miss the availability of active cruise control, too.

What's New?

The 2018 Chevrolet Equinox is all-new this year. Based on an all-new architecture, it's smaller than its predecessor, but still offers about the same interior space. The 1.5-liter turbocharged 4-cylinder is supplemented by a more powerful 2.0-liter turbo and a fuel-efficient 1.6-liter turbocharged diesel.

With the 2018 Chevrolet Equinox, GM has brought to market an extremely competitive compact crossover SUV. Smaller than its predecessor, the new Equinox is still similar in size to rivals like the Honda CR-V, Toyota RAV4 and Mazda CX-5, with a roomy and comfortable interior. Standard is a 1.5-liter turbocharged 4-cylinder that's easily competitive with the rest of the competition, and if power is your thing, a 252-horsepower turbocharged 2.0-liter with a fuel-smart 9-speed automatic transmission is also available. A 1.6-liter diesel engine is also an option, with an estimated 39 mpg on the highway. On the tech side, there's standard Apple CarPlay and Android Auto, and available active safety features like lane-keeping assist and an around-view camera. Unfortunately, they're an option on the most expensive Equinox Premier, pushing the price well beyond its competitors.

▼

Read Full Review

Advertisement

Advertisement

Advertisement

Advertisement

New Chevrolet Equinox Deals and Incentives

LEASE

\$299 /mo | 36 months | Due at Signing

Lease a new 2027 CHEVROLET Equinox 2WD LT for \$299/month for 36 Months with \$3,299 Due at Signing.

[See more details](#)

End Date: 09/30/2026

[See All Current Equinox Deals](#) →

2018 Chevrolet Equinox KBB.com Consumer Reviews

3.9 Consumer Rating [Based on 157 Consumer Reviews](#)

[Write a Review](#)

68% Recommend this vehicle



[Read Consumer Reviews](#)

Advertisement

Cars You May Like

We've rounded up cars that could be your perfect match.

Used 2018

Chevrolet Equinox LT

\$17,941

 GREAT PRICE

Reduced

Brunswick Auto Mart

Confirm Availability 

Used 2018

Chevrolet Equinox Premier

\$13,641

 GOOD PRICE

Hyundai of Bedford

Confirm Availability 

Used 2018

Chevrolet Malibu LT w/
Driver Confidence Package

\$14,900

 GREAT PRICE

Reduced

Byers Volvo, LLC

Confirm Availability 

Used

Ch

\$2

Kia c

←

→

[Browse All Listings](#) →

Advertisement

Advertisement

2018 Chevrolet Equinox Values and Prices

Style	Trade-In Value	Private Party Value	Fair Purchase Price
L Sport Utility 4D	\$6,950	\$8,900	\$10,100
LS Sport Utility 4D	\$6,425	\$8,925	\$10,050
LT Sport Utility 4D	\$7,550	\$10,400	\$11,700
Premier Sport Utility 4D	\$8,000	\$11,250	\$12,700

Values above are based on "Good" condition vehicles ⓘ. Estimated Trade-In Values range from about \$6,425 to \$8,000 depending on vehicle style. Estimated Private Party Values range from about \$8,900 to \$11,250 depending on vehicle style. Values and prices are based on national averages and typical mileage for this model, but they can vary greatly according to mileage, condition, location, and other factors. Valid through 9/22/2026.



Trade-In Value

Trade-In Value is the amount you can expect to receive this week when trading in your vehicle at a dealership.



Private Party Value

Private Party Value is the fair price you can expect when selling your car to an individual, not to a dealer.



Fair Purchase Price

Fair Purchase Price shows what others in your area are actually paying for this vehicle.

[See Full Specs for All 2018 Chevrolet Equinox Styles](#) →

Advertisement

2018 Chevrolet Equinox Depreciation

Advertisement

Login or create a new account to see your vehicle depreciation forecast data.

Historical ———— Forecast - - - -

2018 Chevrolet Equinox

Compare up to 3 vehicles by logging in.

Log In / Sign Up

2018 Chevrolet Equinox Annual Depreciation ⓘ

Year	Vehicle Depreciation*	Resale Value	Trade-In Value
2023	\$3,852	\$12,948	\$10,590
2024	\$2,120	\$10,828	\$8,447
2025	\$592	\$10,236	\$7,956
Now	\$1,336	\$8,900	\$6,950
 Unlock Forecast		2-Year Forecasted Depreciation	
*Depreciation for the last 12 months of the private party resale value.			

2018 Chevrolet Equinox Depreciation

Annual Depreciation is an estimation of what your vehicle's value might be over time based on an average of similar vehicles. Estimations are calculated by comparing Kelley Blue Book Private Party Values of vehicles similar to yours over time, as well as forecasts from Manheim Auction data comparing current and projected auction values against current Kelley Blue Book Private Party and Trade-In Values. This is not a

Already Own This Car?

[Get My Car's Value](#) →

[See Cars for Sale](#)



Calculate Your Budget With These KBB.com Tools

[Car Financing 101](#) →

[Car Loan Calculator](#) →

[Car Lease Calculator](#) →

[Car Affordability Calculator](#) →

Specifications

Fuel Economy City 26 mpg/Hwy 32 mpg/Comb 28 mpg	Fuel Type Gas
Basic Warranty 3 years or 36000 miles	Max Seating 5
Horsepower 170 @ 5600 RPM	Cargo Space 63.5 cu.ft.

▼

[Read More](#)

2018 Chevrolet Equinox Safety

Safety Features & Technology

- Child Door Locks
 - Child Seat Anchors
 - Driver Airbag
 - Passenger Airbag
 - Stability Control
- Emergency & Security Services
 - Front Head Curtain Airbag
 - Front Side Airbag
 - Parental Control System
 - Rear Head Curtain Airbag

5.0

Crash Test Rating

Provided by the National Highway Traffic Safety Administration

Frontal Crash	5.0	Side Barrier	5.0
Rollover Rating	4.0	Side Crash	5.0

Compare to Similar Vehicles

	 Used 2018 Chevrolet Equinox See Details	 Used 2018 Nissan Rogue See Details	 Used 2018 GMC Terrain See Details	 New 2027 Chevrolet Equinox See Details
Price	\$10,100	\$12,050	\$11,500	\$30,995
KBB.com Rating	4.4	4.3	4.5	3.9
Consumer Rating	3.9	4.1	3.9	3.3
Fuel Economy	City 26/Hwy 32/Comb 28 MPG	City 26/Hwy 33/Comb 29 MPG	City 26/Hwy 30/Comb 28 MPG	City 25/Hwy 29/Comb 27 MPG
Fuel Type	Gas	N/A	N/A	Gas
Safety Rating	5.0	4.0	5.0	N/A
Seating Capacity	5	5	5	5
Basic Warranty	3 years or 36000 miles	3 years or 36000 miles	3 years or 36000 miles	3 years or 36000 miles
Horsepower	170 @ 5600 RPM	170 @ 6000 RPM	170 @ 5600 RPM	175 @ 5600 RPM
Engine	4-Cyl, Turbo, 1.5 Liter	4-Cyl, 2.5 Liter	4-Cyl, 1.5 Liter	4-Cyl, Turbo, 1.5 Liter
Drivetrain	FWD	FWD	FWD	FWD

[Compare More](#) →

2018 Chevrolet Equinox Rankings

Rank	Vehicles	HP
#1	2018 Volkswagen Tiguan	184
#2	2018 Ford Escape	179
#3	2019 Dodge Journey	173
#4	2018 Chevrolet Equinox	170
#5	2023 Hyundai NEXO	161

More Chevrolet Equinox News & Information

Compact SUV Crossover

Our 3 Favorite Things About the 2026 Chevrolet Equinox

The 2026 Chevrolet Equinox compact SUV brings practicality, ample tech, and bold design.

Matt Degen | June 17, 2026

Compact SUV Crossover

2025 Chevrolet Equinox Starts Under \$30,000

There's an affordability crisis in the car industry. But Chevrolet is pushing back. As interest rates have soared, automakers concluded...

Sean Tucker | April 29, 2024

Compact SUV Crossover

Tests: Emergency Braking Struggles

Car safety technology keeps advancing. To keep pace, one of America's major car safety watchdogs keeps coming up with tougher...

Sean Tucker | April 25, 2024

FAQs

Is the 2018 Chevrolet Equinox a good vehicle?

Yes, the 2018 Chevrolet Equinox is a good car, as reflected by its above-average Kelley Blue Book rating of 4.4 out of 5.

What is the MPG for a 2018 Chevrolet Equinox?

The 2018 Chevrolet Equinox is rated to return city/highway fuel economy of 26/32 mpg.

How much should a 2018 Chevrolet Equinox cost?

Used 2018 Chevrolet Equinox prices currently range from \$10,100 for the LS Sport Utility 4D to \$12,700 for the Premier Sport Utility 4D when purchasing from a dealership, depending on a range of factors like equipment, mileage, and condition.

The 2018 Chevrolet Equinox is part of the 3rd-generation Equinox, which our owners give an above-average reliability rating of 4 out of 5.

Also from Chevrolet

2018 Chevrolet Bolt EV

2018 Chevrolet Camaro

2018 Chevrolet City Express

2018 Chevrolet Colorado Crew Cab

2018 Chevrolet Colorado Extended Cab

2018 Chevrolet Corvette

2018 Chevrolet Cruze

2018 Chevrolet Express 2500 Cargo

2018 Chevrolet Express 2500 Passenger

2018 Chevrolet Express 3500 Cargo

2018 Chevrolet Express 3500 Passenger

2018 Chevrolet Impala

2018 Chevrolet Malibu

2018 Chevrolet Silverado 1500 Crew Cab

2018 Chevrolet Silverado 1500 Double Cab

2018 Chevrolet Silverado 1500 Regular Cab

2018 Chevrolet Silverado 2500 HD Crew Cab

2018 Chevrolet Silverado 2500 HD Double Cab

2018 Chevrolet Silverado 2500 HD Regular Cab

2018 Chevrolet Silverado 3500 HD Crew Cab

2018 Chevrolet Silverado 3500 HD Double Cab

2018 Chevrolet Silverado 3500 HD Regular Cab

2018 Chevrolet Sonic

2018 Chevrolet Spark

2018 Chevrolet Traverse

2018 Chevrolet Trax

2018 Chevrolet Volt

[FAQ](#) | [Contact Us](#) | [Privacy Notice](#) | [Do Not Sell or Share My Personal Information](#) | [Limit the Use of My Sensitive Personal Information](#) |

[Manage Cookies](#) | [About Us](#) | [Careers](#) | [Corporate](#) | [Marketing and Advertising Solutions](#) | [Media](#) | [Site Map](#) | [KBB Brazil](#)

| [KBB Canada](#)

Kelley Blue Book, a Cox Automotive Company

© 1995-2026 Kelley Blue Book Co.®, Inc. All rights reserved.

[Copyrights & Trademarks](#) | [Vehicle Photos © Evox Images](#) | [Terms of Service](#) | [Linking Policy](#) | [Accessibility Statement](#)



Home / Vehicle ratings / 2018 Chevrolet Equinox 4-door SUV

2018 Chevrolet Equinox

SMALL SUV / 4-DOOR SUV



Crashworthiness

Small overlap front: driver-side	G
Small overlap front: passenger-side	G
Moderate overlap front: original test	G
Side: original test	G
Side: updated test	M
Roof strength	G
Head restraints & seats	G

Crash avoidance & mitigation

Headlights	M
Front crash prevention: vehicle-to-vehicle	
Optional system	

Seat belts & child restraints

LATCH ease of use	A
-------------------	---

Other available safety features

- Optional blind spot detection
- Optional lane departure warning
- Optional lane departure prevention

Key		
	G Good	Superior
	A Acceptable	Advanced
	M Marginal	Basic
	P Poor	

Some ratings use a scale of Poor to Good. Others range from Basic to Superior.

Small overlap front: driver-side

Tested vehicle: **2018 Chevrolet Equinox LT 4-door 4wd**
Rating applies to 2018-24 models

The Chevrolet Equinox and GMC Terrain were redesigned for the 2018 model year. Both vehicles are smaller and lighter than the earlier design and therefore are now classified as small SUVs. Driver-side small overlap frontal ratings are assigned by the Institute based on a test conducted by General Motors.

Overall evaluation	G
Structure and safety cage	G
Driver injury measures	
Head/neck	G
Chest	G
Hip/thigh	G
Lower leg/foot	G
Driver restraints and dummy kinematics	G

► Technical measurements for this test

Small overlap front: passenger-side

Tested vehicle: **2018 Chevrolet Equinox LS 4-door 4wd**
Rating applies to 2018-24 models

The Chevrolet Equinox and GMC Terrain were redesigned for the 2018 model year. Both vehicles are smaller and lighter than the earlier design and therefore are now classified as small SUVs.


Overall evaluation	G
Structure and safety cage	A
Passenger injury measures	
Head/neck	G
Chest	G
Hip/thigh	G
Lower leg/foot	A
Passenger restraints and dummy kinematics	G
Driver injury measures	
Head/neck	G
Chest	G
Hip/thigh	G
Lower leg/foot	G
Driver restraints and dummy kinematics	G



Action shot taken during the passenger-side small overlap frontal crash test.



The dummy's position in relation to the door frame and dashboard after the crash test indicates that the passenger's survival space was maintained reasonably well.



The frontal and side curtain airbags worked well together to keep the passenger dummy's head from coming close to any stiff structure or outside objects that could cause injury.



Intrusion of the dashboard and door hinge pillar contributed to a moderate risk of injury to the right lower leg.

► Technical measurements for this test

Moderate overlap front: original test

Tested vehicle: **2018 Chevrolet Equinox Premier 4-door 4wd**

Rating applies to 2018-24 models

The Chevrolet Equinox and GMC Terrain were redesigned for the 2018 model year. Both vehicles are smaller and lighter than the earlier design and therefore are now classified as small SUVs. Moderate overlap frontal ratings are assigned by the Institute based

on a test conducted by General Motors.

Overall evaluation	G
Structure and safety cage	G
Driver injury measures	
Head/neck	G
Chest	G
Leg/foot, left	G
Leg/foot, right	G
Driver restraints and dummy kinematics	G

► Technical measurements for this test

Side: original test

Tested vehicle: **2018 Chevrolet Equinox Premier 4-door 4wd**

Rating applies to 2018-24 models

The Chevrolet Equinox and GMC Terrain were redesigned for the 2018 model year. Both vehicles are smaller and lighter than the earlier design and therefore are now classified as small SUVs. Side ratings are assigned by the Institute based on a test conducted by General Motors.

Overall evaluation	G
Structure and safety cage	G
Driver injury measures	
Head/neck	G
Torso	G
Pelvis/leg	G
Driver head protection	G
Rear passenger injury measures	
Head/neck	G
Torso	G
Pelvis/leg	G

Rear passenger head protection**G**

► Technical measurements for this test

Side: updated test

Tested vehicle: **2021 Chevrolet Equinox LS 4-door 4wd**

Rating applies to 2018-24 models

The Chevrolet Equinox and GMC Terrain were redesigned for the 2018 model year. Both vehicles are smaller and lighter than the earlier design and therefore are now classified as small SUVs.

Overall evaluation**M****Structure and safety cage****G****Driver injury measures**

Head/neck

G

Torso

M

Pelvis

G**Driver head protection****G****Rear passenger injury measures**

Head/neck

A

Torso

A

Pelvis

G**Rear passenger head protection**

The dummy's head contacted the C-pillar hard, through the side curtain airbag. The head protection is inadequate.

M



View of the vehicle just after the crash test.



View of the vehicle after the crash with doors removed, showing the side airbags and damage to the occupant compartment.



Smeared greasepaint shows where the driver dummy's head was protected from being hit by hard structures by the side airbags.



The dummy's head contacted the C-pillar through the side curtain airbag.

► Technical measurements for this test

Roof strength

Tested vehicle: **2018 Chevrolet Equinox Premier 4-door 4wd**

Rating applies to 2018-23 models

Overall evaluation

G

Curb weight	3,460 lbs
Peak force	18,196 lbs
Strength-to-weight ratio	5.26

Head restraints & seats

Seat type: Power leather seat

Overall evaluation	G
Dynamic rating	G
Seat/head restraint geometry	G

► Technical measurements for this test


Headlights

Ratings are given for 4 different headlight variations available on this vehicle.

(1) Trim level(s): LT trim

Low-beam headlight type	HID projector
High-beam headlight type	HID projector
Curve-adaptive?	No
High-beam assist?	No
Overall rating	M

Distance at which headlights provide at least 5 lux illumination:



Low beams

On the straightaway, visibility was fair on both sides of the road. On curves, visibility was fair on both right curves and inadequate on both left curves.

The low beams never exceeded glare limits.

High beams

On the straightaway, visibility was good on the right side of the road and inadequate on the left side. On curves, visibility was inadequate in all 4 tests.

► Technical measurements for this test

(2) Trim level(s): Premier trim equipped with Confidence and Convenience II package

Low-beam headlight type LED projector


High-beam headlight type LED projector

Curve-adaptive? No

High-beam assist? Yes

Overall rating **M**

Distance at which headlights provide at least 5 lux illumination:



Low beams

On the straightaway, visibility was good on both sides of the road. On curves, visibility was inadequate in all 4 tests.

The low beams never exceeded glare limits.

High beams

On the straightaway, visibility was inadequate on both sides of the road. On curves, visibility was inadequate in all 4 tests.

High-beam assist compensates for some limitations of this vehicle's low beams on the straightaway, on both left curves and on both right curves.

► Technical measurements for this test

(3) Trim level(s): Premier trim

Low-beam headlight typeLED projector


High-beam headlight typeLED projector

Curve-adaptive?No

High-beam assist?No

Overall ratingM

Distance at which headlights provide at least 5 lux illumination:



Low beams

On the straightaway, visibility was good on both sides of the road. On curves, visibility was inadequate in all 4 tests.

The low beams never exceeded glare limits.

High beams

On the straightaway, visibility was inadequate on both sides of the road. On curves, visibility was inadequate in all 4 tests.

► Technical measurements for this test

(4) Trim level(s): L trim, LS trim

Low-beam headlight typeHalogen projector


High-beam headlight typeHalogen projector

Curve-adaptive?No

High-beam assist?No

Overall ratingM

Distance at which headlights provide at least 5 lux illumination:



Low beams

On the straightaway, visibility was good on both sides of the road. On curves, visibility was inadequate in all 4 tests.

The low beams never exceeded glare limits.

High beams

On the straightaway, visibility was good on the right side of the road and inadequate on the left side. On curves, visibility was inadequate in all 4 tests.

► Technical measurements for this test

Front crash prevention: vehicle-to-vehicle

System details

- optional Low Speed Forward Automatic Braking
- optional Forward Collision Alert

Package name

- optional Confidence and Convenience II Package

Overall evaluation

SUPERIOR
WITH
OPTIONAL
EQUIPMENT

Applies to 2018-19 models


- This system meets the requirements for forward collision warning.
- In the 12 mph test, this vehicle avoided a collision.
- In the 25 mph test, impact speed was reduced by 22 mph.

Child seat anchors

Rating applies to 2018-24 models

Overall evaluation	A
Vehicle trim	LS
Seat type	cloth

This vehicle has 2 rear seating positions with complete child seat attachment (LATCH) hardware. It has 1 additional seating position with a tether anchor only.



Details by seating position

- 1

Tether anchor

easy-to-find location

other hardware could be confused for anchor

Lower anchors

not too deep in seat

not too much force needed to attach

easy to maneuver around anchors
- 2

Tether anchor

easy-to-find location

other hardware could be confused for anchor

Lower anchors

none available
- 3

Tether anchor

- G

Good
- A

Acceptable
- M

Marginal
- P

Poor
- ☐

Seating positions that rely on borrowed lower anchors or have only a tether anchor available

are not rated.

Tether anchor

Lower anchors

Lower anchor(s) can be borrowed from adjacent positions(s)

☐ No hardware available

easy-to-find location

other hardware could be confused for anchor

Lower anchors

not too deep in seat

not too much force needed to attach

easy to maneuver around anchors

► Technical measurements for this test



Vehicle ratings

News

Research areas

Who we are

Member groups

Careers

Media resources

Contact us

A free resource for students and teachers [↗](#)

Learn about the initiative

Making roads and vehicles safer for everyone.

The **Insurance Institute for Highway Safety (IIHS)** is an independent, nonprofit scientific and educational organization dedicated to reducing deaths, injuries and property damage from motor vehicle crashes through research and evaluation and through education of consumers, policymakers and safety professionals.

The **Highway Loss Data Institute (HLDI)** shares and supports this mission through scientific studies of insurance data representing the human and economic losses resulting from the ownership and operation of different types of vehicles and by publishing insurance loss results by vehicle make and model.

Both organizations are wholly supported by [these auto insurers and insurance associations](#).

©1996-2026, Insurance Institute for Highway Safety, Highway Loss Data Institute, 501(c)(3) organizations | [Copyright information and privacy policy](#).