WE HAVE TRIED OUR BEST TO ENSURE THE ACCURACY OF THE INFORMATION LISTED BELOW, BUT MISTAKES DO HAPPEN. PRIOR TO PURCHASE, BUYER SHOULD VERIFY ALL THE OPTIONS LISTED BELOW TO BE ACCURATE. WE MAKE NO REPRESENTATION TO THE ACCURACY OF THIS INFORMATION.

FRED MARTIN SUPERSTORE

fredmartinsuperstore.com

FINANCING AVAILABLE!†

AutoCheck BUYBACK Protection

Request an AutoCheck© Vehicle History Report To See The Detailed History On Any Car, Truck, Van or SUV In Seconds!

LIFETIME LIMITED POWERTRAIN WARRANTY*

*SOME RESTRICTION APPLY SEE BELOW.

ALL TRADE-INS WELCOME!

2020 Lincoln Aviator Reserve Premium AWD

Odometer: 67,680
Engine: 3.0L V6
Color: Pearl Metallic
Interior: Medium Slate Leather

Transmission: 10-Speed Automatic
VIN: 5LM5J7XC9LGL00278
Stock #: 1C263857AP
Drivetrain: AWD

COMFORT EQUIPMENT AND ACCESSORIES

Safety

4-Wheel Disc Brakes
ABS brakes
Adaptive Steering
Dual front impact airbags
Dual front side impact airbags
Emergency communication system: SYNC 3 911 Assist
Front anti-roll bar
Knee airbag

Additional

3-ROW 7-PASSENGER SEATING
APPLE CARPLAY & ANDROID AUTO
PANORAMIC SUNROOF
NAVIGATION
ALL-WHEEL DRIVE
22" ALLOY WHEELS
CLASS IV TRAILER TOW PACKAGE
FACTORY REMOTE START
10.1" TOUCH SCREEN

Exterior

Power Liftgate
Auto High-beam Headlights
Delay-off headlights
Front fog lights
Fully automatic headlights
Adaptive Pixel LED Headlamps
Adaptive Suspension w/Road Preview
Air Glide Suspension w/Dynamic Lower Entry
Auto-dimming door mirrors

Electronic

Navigation System
14 Speakers
AM/FM radio: SiriusXM
Audio memory
Radio data system
Radio: Revel AM/FM Audio System w/14 Speakers
Radio: Revel Ultima 3D Audio System w/28 Speakers
Rear audio controls

Technical

Adaptive suspension
Four wheel independent suspension
Traction control
250 Amps Alternator

Interior

Air Conditioning
Automatic temperature control
Front dual zone A/C
HVAC memory
Rear air conditioning
Rear dual zone A/C
Rear window defroster
2nd Row Bench Seat

GET PRE-QUALIFIED NOW!
THIS WILL NOT IMPACT OR EFFECT YOUR CREDIT SCORE!

For More Information, Check Out This Vehicle Online

NO-CHARGE EXTRAS!*

- 3 YEARS OF FREE OIL CHANGES*
- 15 DAY LOVE IT OR LEAVE IT RETURN GUARANTEE*
- 3 YEARS OF FREE ROADSIDE ASSISTANCE*
- FREE AUTOCHECK® VEHICLE HISTORY REPORT WITH BUYBACK PROTECTION*
- NO LEMON GUARANTEE*

IT IS THE RESPONSIBILITY OF THE PURCHASER TO VERIFY THE OPTIONS LISTED ON THIS LABEL ARE CORRECT PRIOR TO BUYING THIS VEHICLE. ALTHOUGH WE HAVE USED A COMPUTER SCREENING PROCESS TO ENSURE THE ACCURACY OF THIS LABEL THE PURCHASER MUST VERIFY THE EQUIPMENT LISTED ON THIS LABEL IS ACTUALLY ON THE VEHICLE, AS MISTAKES DO OCCUR. THE NO CHARGE ITEMS LISTED ABOVE AND AN * (ASTERISK) APPLY TO SELECT VEHICLES WITH A FINAL SELLING PRICE OF $12,000.00 OR ABOVE BEFORE TAX, TITLE, AND DOCUMENTARY FEE. EACH OF THE ITEMS LISTED WITH AN * (ASTERISK) HAVE A WRITTEN DOCUMENT DETAILING THEIR BENEFITS AND SHOULD BE READ AND UNDERSTOOD BY THE PURCHASER PRIOR THE PURCHASING THIS VEHICLE. † WITH APPROVED CREDIT.

Experian AutoCheck Report

Report run: 11/06/2026 10:19:01 EST

This report is brought to you by:

Fred Martin Superstore **ELITE MEMBER**

3195 Barber Rd Norton, OH 44203

330.753.4444

2020 Lincoln Aviator Reserve

SUV 4D (3.0L V6 DI Gasoline)

VIN:	5LM5J7XC9LGL00278
Class:	SUV - Large Luxury
Country of Assembly:	United States
Vehicle Age:	6 year(s)
Estimated In Service:	06/12/2019
Last Reported Odometer:	67,701 (10/29/2026)

Owners - 3

Vehicle Usage

Lease, Rental

90 **93** 95

AutoCheck Score

Similar vehicles usually range between **90 and 95**

Vehicle History at a Glance

State Title Brand

CLEAN

Auction Brand / Issues

NO ISSUE

Accident / Damage

No Accidents or Damage Reported

NO ISSUE

Open Recall Check

3 OPEN RECALL(S)

Insurance Loss / Transfer

NO ISSUE

Odometer Check

Last reported odometer:
67,701 (10/29/2026)

NO ISSUE

Certified Pre-Owned

NO CPO INFO AVAILABLE

Service / Repair

31 Service Record(s) Reported

NO ISSUE

Additional History

Lien Reported

EVENTS REPORTED

AutoCheck Assured™

This vehicle is AutoCheck Assured™

This vehicle does not have any state title brands or other major problems reported.

Learn More

Accident & Damage

Your Vehicle Checks Out There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.



Open Recall Check

Information Reported: AutoCheck found 3 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 03/05/2026

Recall Type - Safety

NHTSA / OEM Recall No. - 26V123 / 26C11

Campaign Description - Safety Compliance: SYNC SCREEN UPDATE
Status: Remedy Available

Recall Date - 06/26/2026

Recall Type - Safety

NHTSA / OEM Recall No. - 26V402 / 26S48

Campaign Description - Safety Recall: TRANSMISSION PARKING SYSTEM INSPECTION
Status: Remedy Available

Recall Date - 07/17/2026

Recall Type - Safety

NHTSA / OEM Recall No. - 26V451 / 26S52

Campaign Description - Safety Recall: SECOND-ROW SEAT EASY ENTRY SWITCH HOUSING AND BEZEL REPLACEMENT
Status: Remedy Not Available

More information including remedy or risk factors. Locate your nearest authorized Lincoln Dealer to schedule repair.

Service History

Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.

Regular Oil Changes

- 3 oil services reported

Fluids Maintained

- 2 coolant flushes

OEM Recommended Services

- Last oil service reported 06/17/2025

- Last fluid maintained 08/29/2026

Brakes Maintained

- 2 brake pad replacements
- Brake last maintained on 06/17/2025

Tires Maintained

Information not available.

A/C & Climate Control

- 1 A/C services reported
- A/C system last serviced 09/12/2019

Other Services

- Cabin air filter replaced on 05/05/2026
- Battery replaced on 12/07/2021

65000 Mile Service

- Adjust Tire Pressure
- Balance Tires
- Inspect & Adjust All Fluids

70000 Mile Service Not Yet Due

- Adjust Tire Pressure
- Balance Tires
- Inspect & Adjust All Fluids

Odometer Check

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

State Title Odometer Check

No issues reported

Auction Odometer Check

No issues reported

Odometer Calculation Check

No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.
Vehicle: 2020 Lincoln Aviator Reserve (5LM5J7XC9LGL00278) **Report Run Date:** 11/06/2026 10:19:01 EST

2019

Vehicle Prep and Other Pre-Titling Events

Preparation Date: 06/2019

Event Date	Location	Odometer	Data Source	Details
06/12/2019			Independent Source	Vehicle Manufactured and Shipped to Dealer
09/12/2019	OH	5	Service Record	Cooling System Serviced Vehicle Inspected Vehicle Recall Service Performed Vehicle Detailed

2020

Owner 1

Location: OH | Owned From: 01/2020 | Usage: Lease, Rental

Event Date	Location	Odometer	Data Source	Details
01/15/2020	CINCINNATI, OH	10	Motor Vehicle Dept.	Title(Title #:8302827533) (Leased Vehicle)(Lien Reported) Rental
01/16/2020	CINCINNATI, OH		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle) Rental
02/18/2020	OH	3,942	Service Record	Electrical System Serviced
06/05/2020	CINCINNATI, OH	7,230	Dealer Record	Vehicle in Dealer Inventory
07/15/2020	CINCINNATI, OH		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle) Rental
11/02/2020	CINCINNATI, OH		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle) Rental

Event Date	Location	Odometer	Data Source	Details
03/16/2021	OH	19,573	Service Record	Vehicle Inspected Air Filter Changed Battery Serviced or Replaced Vehicle Detailed Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
06/14/2021	CINCINNATI, OH		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle) Rental
12/07/2021	OH	28,643 28,644	Service Record	Vehicle Inspected Air Filter Changed Battery Serviced or Replaced Vehicle Recall Service Performed Recommended Maintenance Performed Wipers Replaced And/Or Serviced Electrical System Serviced Lube, Oil And/Or Filter Changed Vehicle Serviced or Inspected
12/22/2021	CINCINNATI, OH		Motor Vehicle Dept.	Title(Title #:8303120829) (Leased Vehicle)
12/29/2021	OH	29,251	Service Record	Vehicle Inspected Vehicle Recall Service Performed Recommended Maintenance Performed Promotional Service Performed
03/02/2022	OH	29,271	Service Record	Vehicle Inspected Accessories Serviced or Installed
03/03/2022	OH	29,272	Service Record	Vehicle Serviced or Inspected

2022

Owner 2

Location: OH | Owned From: 03/2022 | Usage: Personal

Event Date	Location	Odometer	Data Source	Details
03/22/2022	HAMILTON, OH	29,365	Motor Vehicle Dept.	Title(Title #:8303153850) (Lien Reported)
03/24/2022	HAMILTON, OH		Motor Vehicle Dept.	Registration Event/Renewal
03/25/2022	OH	30,227	Service Record	Tires or Wheels Service Performed
05/24/2022		33,142	Service Record	Fuel System Serviced Multiple Point Vehicle Inspection
09/07/2022	OH	38,506	Service Record	Vehicle Inspected Recommended Maintenance Performed Vehicle Detailed
01/09/2023	HAMILTON, OH		Motor Vehicle Dept.	Registration Event/Renewal
03/16/2023	OH	46,769	Service Record	Vehicle Inspected Air Filter Changed Vehicle Detailed Wipers Replaced And/Or Serviced
06/20/2023			Manufacturer	Manufacturer Service Bulletin Mfr. Recall 22M03 Customer Satisfaction Program - Multi Repair: REPLACE FRONT AND OR SIDE CAMERAS IF FOGGY LOCATE YOUR NEAREST AUTHORIZED **LINCOLN DEALER** TO SCHEDULE REPAIR. Status: Remedy Unknown
07/06/2023	OH	50,270	Service Record	Vehicle Inspected Recommended Maintenance Performed Vehicle Detailed Chassis Serviced Electrical System Serviced Suspension Serviced
07/25/2023	OH	50,584	Service Record	Vehicle Inspected Recommended Maintenance Performed Vehicle Detailed Chassis Serviced Electrical System Serviced Suspension Serviced Tires or Wheels Service Performed
08/23/2023	ONLINE DEALER	52,156	Dealer Listing	Vehicle Listed for Sale
08/29/2023	OH	52,156	Service Record	Vehicle Recall Service Performed
09/07/2023	YOUNGSTOWN, OH	52,156	Motor Vehicle Dept.	Title(Title #:5004229098) (Lien Reported)
09/18/2023	PA	52,208	Auto Auction	Reported at Auto Auction as Dealer Vehicle
09/21/2023	PA	52,208	Auto Auction	Reported at Auto Auction

Event Date	Location	Odometer	Data Source	Details
10/09/2023	GIBSONIA, PA	52,208	Motor Vehicle Dept.	Title(Title #:86451989)
10/11/2023	CUYAHOGA FALLS, OH	52,548 †	Dealer Listing	Vehicle Listed for Sale
10/16/2023	CUYAHOGA FALLS, OH	52,453	Motor Vehicle Dept.	Title(Title #:6702911838) (Lien Reported)
10/04/2024	BARBERTON, OH		Motor Vehicle Dept.	Title(Title #:7709671060) (Lien Reported)
10/04/2024	ONLINE DEALER	53,014	Dealer Listing	Vehicle Listed for Sale
10/16/2024		53,119	Fred Martin Superstore 330.753.4444	Multiple Point Vehicle Inspection Recommended Maintenance Performed Vehicle Detailed
10/16/2024	KY	53,119	Service Record	Vehicle Inspected

2024

Owner 3

Location: OH | Owned From: 10/2024 | Usage: Personal

Event Date	Location	Odometer	Data Source	Details
10/22/2024	UNIONTOWN, OH	53,014 †	Motor Vehicle Dept.	Title(Title #:7709682850) (Lien Reported)
06/17/2025		55,929	Fred Martin Superstore 330.753.4444	Fuel System Serviced Multiple Point Vehicle Inspection Recommended Maintenance Performed Brakes Serviced Electrical System Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Promotional Service Performed
01/08/2026	KY	57,759	Service Record	Vehicle Serviced or Inspected
01/20/2026		58,478	Fred Martin Superstore 330.753.4444	Vehicle Detailed
01/23/2026		58,629	Fred Martin Superstore 330.753.4444	Multiple Point Vehicle Inspection Tires or Wheels Service Performed
01/23/2026	KY	58,629	Service Record	Vehicle Inspected
01/26/2026		58,000 †	Fred Martin Superstore 330.753.4444	Vehicle Serviced or Inspected
01/30/2026	OH	58,726	Service Record	Electrical System Serviced
02/16/2026		59,447	Fred Martin Superstore 330.753.4444	Multiple Point Vehicle Inspection Tires or Wheels Service Performed
02/16/2026	OH	59,447	Service Record	Vehicle Inspected
03/05/2026			Manufacturer	Manufacturer Recall NHTSA Recall 26V123 / Mfr. Recall 26C11 Safety Compliance: SYNC SCREEN UPDATE LOCATE YOUR NEAREST AUTHORIZED **LINCOLN DEALER** TO SCHEDULE REPAIR. Status: Remedy Available
03/05/2026		60,098	Fred Martin Superstore 330.753.4444	Multiple Point Vehicle Inspection Tires or Wheels Service Performed
03/09/2026	OH	60,098	Service Record	Vehicle Inspected Tires or Wheels Service Performed
03/27/2026	OH	61,000	Independent Emission Source	Passed Emission Inspection
04/10/2026		62,260	Fred Martin Superstore 330.753.4444	Multiple Point Vehicle Inspection Vehicle Detailed Vehicle Fluids Serviced Promotional Service Performed
04/10/2026	OH	62,260	Service Record	Vehicle Inspected
05/05/2026		63,978	Fred Martin Superstore 330.753.4444	Air Filter Changed Body Service Performed
06/26/2026			Manufacturer	Manufacturer Recall NHTSA Recall 26V402 / Mfr. Recall 26S48 Safety Recall: TRANSMISSION PARKING SYSTEM INSPECTION LOCATE YOUR NEAREST AUTHORIZED **LINCOLN DEALER** TO SCHEDULE REPAIR. Status: Remedy Available

Event Date	Location	Odometer	Data Source	Details
07/17/2026			Manufacturer	Manufacturer Recall NHTSA Recall 26V451 / Mfr. Recall 26S52 Safety Recall: SECOND-ROW SEAT EASY ENTRY SWITCH HOUSING AND BEZEL REPLACEMENT LOCATE YOUR NEAREST AUTHORIZED **LINCOLN DEALER** TO SCHEDULE REPAIR. Status: Remedy Not Available
08/29/2026	OH	66,029	Service Record	Vehicle Inspected Vehicle Detailed Vehicle Fluids Serviced Promotional Service Performed
10/29/2026	BARBERTON, OH	67,701	Dealer Listing	Vehicle Listed for Sale

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

Warranty Check

To see your estimated warranty coverage details, please enter a mileage reading below. The warranty coverage shown is an estimate using the best available in-service date, the mileage reading you enter, and warranty information. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to **AutoCheck Terms and Conditions**. If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.

Here is a list of some major defects that may occur in used vehicles.

Frame & Body
- Frame-cracks, corrective welds, or rusted through
- Dog tracks—bent or twisted frame

Engine
- Oil leakage, excluding normal seepage
- Cracked block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

Transmission & Drive Shaft
- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear
- Manual clutch slips or chatters

Differential
- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

Cooling System
- Leakage including radiator
- Improperly functioning water pump

Electrical System
- Battery leakage
- Improperly functioning alternator, generator, battery, or starter

Fuel System
- Visible leakage

Inoperable Accessories
- Gauges or warning devices
- Air conditioner
- Heater & Defroster

Brake System
- Failure warning light broken
- Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserve (DOT spec.)
- Does not stop vehicle in straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Structural or mechanical parts damaged

Air Bags

Steering System
- Too much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jams
- Front wheels aligned improperly (DOT specs.)
- Power unit belts cracked or slipping
- Power unit fluid level improper

Suspension System
- Ball joint seals damaged
- Structural parts bent or damaged
- Stabilizer bar disconnected
- Spring broken
- Shock absorber mounting loose
- Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

Tires
- Tread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

Wheels
- Visible cracks, damage or repairs
- Mounting bolts loose or missing

Exhaust System
- Leakage
- Catalytic Converter

Fred Martin Motor Company
DEALER NAME

3195 Barber Rd, Barberton, Ohio 44203
ADDRESS

(330) 753-4444
TELEPHONE

EMAIL

Sales Manager
FOR COMPLAINTS AFTER SALE, CONTACT:

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).

Trade In/Loan/Retail Breakdown
J.D. Power
Publication 11/2026, Region: Central

2020 LINCOLN Aviator Utility 4D Reserve I AWD 3.0L V6 Turbo ..... $22,475 / $20,250 / $26,875

VIN: 5LM5J7XC9LGL00278

Stock #: 1C263857AP

MSRP 58700
Weight 4897

*** Itemized Add/Deducts ***

Heated Rear Seats ..... Included
Cooled Front Seats ..... Included
Cooled Rear Seats ..... Included
Elements Plus Pkg. ..... Included
Towing/Camper Pkg ..... 300 / 300 / 325
W/out Rear Bucket Seats ..... -125 / -125 / -150
Panoramic Power Sunroof ..... Included
Condition ..... Clean
Total Value without mileage ..... $22,650 / $20,425 / $27,050
Mileage adjustment (67680) miles $2,275

*** J.D. Power Trade In/Loan/Retail
$24,925 / $22,700 / $29,325

Fred Martin Motor Company - Rebecca Mowery

J.D. Power publication for Ohio: Publication 11/2026, Region: Central

Values are subjective opinions. J.D. Power and vAuto, Inc. assume no responsibility for errors or omissions.

© vAuto, Inc. 2026, all rights reserved.

Typical Listing Price/Trade In/Private Party/Fair Purchase Price Breakdown

KBB.com

11/06/2026 Edition 44203

2020 Lincoln Aviator Reserve Sport Utility 4D ..... $26,590 / $19,440 / $25,410 / $25,900

VIN: 5LM5J7XC9LGL00278

Stock #: 1C263857AP

*** Itemized Add/Deducts ***

V6, Twin Turbo, 3.0 Liter	Included	Head-Up Display	Included
Automatic, 10-Spd w/SelectShift	Included	AM/FM/HD Radio	Included
AWD	Included	CD/MP3 (Single Disc)	Included
Color: White	120 / 180 / 120 / 120	Revel Premium Sound	Included
Blind-Spot Detection System	Included	Revel Ultima 3D Premium Sound	Included
Reserve I Group	679 / 679 / 679 / 679	SiriusXM Satellite	Included
Elements Plus Pkg	226 / 226 / 226 / 226	Navigation System	Included
Convenience Pkg	Included	SYNC	Included
Dynamic Handling Pkg	413 / 413 / 413 / 413	Backup Camera	Included
Luxury Pkg	454 / 454 / 454 / 454	360-Degree Camera	Included
Illumination Pkg	295 / 295 / 295 / 295	Dual Air Bags	Included
Hill Start Assist	Included	Side Air Bags	Included
Traction Control	Included	F&R Head Curtain Air Bags	Included
AdvanceTrac	Included	Knee Air Bags	Included
ABS (4-Wheel)	Included	Lane Keeping System	Included
Perimeter Alarm System	Included	Heated Seats	Included
Keyless Entry	Included	Ventilated Seats	Included
Keyless Start	Included	Dual Power Seats	Included
Air Conditioning	Included	Leather	Included
Air Conditioning, Rear	Included	Power Third Row	Included
Power Windows	Included	Panoramic Vista Roof	221 / 221 / 221 / 221
Power Door Locks	Included	Daytime Running Lights	Included
Power Close Doors	Included	LED Headlamps	Included
Cruise Control	Included	Fog Lights	Included
Power Liftgate Release	Included	Rear Spoiler	Included
Power Steering	Included	Towing Pkg	103 / 103 / 103 / 103
Tilt & Telescoping Wheel	Included	Oversized Premium Wheels 20"+	171 / 171 / 171 / 171

Condition ..... Excellent*

Total Value without mileage ..... $29,272 / $22,182 / $28,092 / $28,582

Mileage adjustment (67680) miles $2,660

*** KBB.com Typical Listing Price/Trade In/Private Party/Fair Purchase Price
$31,932 / $24,842 / $30,752 / $31,242

*"Excellent" - 3% of all cars we value meet this criteria. This car looks new and is in excellent mechanical condition. It has never had paint or bodywork and has an interior and body free of wear and visible defects. The car is rust-free and does not need reconditioning. Its clean engine compartment is free of fluid leaks. It also has a clean title history, has complete and verifiable service records.

Fred Martin Motor Company - Rebecca Mowery

©2026 Kelley Blue Book Co, Inc. All rights reserved. As of 11/6/2026 Edition for 44203. Values and pricing are the opinion of Kelley Blue Book, and the actual price of a vehicle may vary. The value and pricing information displayed for a particular vehicle is based upon the specification, mileage and/or condition information provided by the person generating this report. Kelley Blue Book assume no responsibility for errors or omissions.

© vAuto, Inc. 2026, all rights reserved.

Sign In

Home > Lincoln > Lincoln Aviator > 2020 Lincoln Aviator

Used 2020 Lincoln Aviator

4.1 Expert 3.8 Consumer Write a Review

Save This Car

Exterior (50)

Interior (61)



2027 2026 2025 2024 2023 2022 2021 **2020** 2005 2004 2003

Fuel Economy
20 - 23 combined mpg

Horsepower
400 - 494 hp

Engine
2 engines available

Towing Capacity
4,500 lbs

Next Steps: Shopping for this car?

See Cars for Sale Build & Price

Get My Car's Value →

2020 Lincoln Aviator Review



By **Lyn Woodward**
Updated December 13, 2023

Pros

- All-new model to the Lincoln line-up
- Elegant luxury styling
- Plug-in hybrid and gasoline-powered options
- Full of innovative tech

Cons

- Doesn't offer a high-performance option
- Heavy vehicle for either powertrain

What's New?

- Aviator is the first 3-row midsize SUV for Lincoln
- "Phone As A Key" is a brand-new available tech feature
- Adaptive suspension with Road Preview capability

#11 in Best Midsize Luxury SUVs of 2020

The 2020 Lincoln Aviator boasts gasoline and plug-in hybrid (PHEV) powertrain options, a luxuriously appointed interior, and seating capacity for up to seven

Read Full Review

Advertisement

Advertisement

Advertisement

2020 Lincoln Aviator KBB.com Consumer Reviews

3.8 Consumer Rating Based on 46 Consumer Reviews

Write a Review

68% Recommend this vehicle

5 ★	63%
4 ★	7%
3 ★	0%
2 ★	13%
1 ★	17%

Read Consumer Reviews

Used Cars

Cars You May Like


We've rounded up cars that could be your perfect match.

Used 2020
Lincoln Corsair AWD

Used 2020
Lincoln Aviator Reserve w/ Equipment Group 202A

Used 2020
Lincoln Aviator Black Label w/ Dynamic Handling Package

Used
Lin Ele



Browse All Listings →

Advertisement

2020 Lincoln Aviator Values and Prices

Style	Trade-In Value	Private Party Value	Fair Purchase Price
Sport Utility 4D	$15,550	$20,700	$22,200
Reserve Sport Utility 4D	$14,050	$20,900	$22,400
Grand Touring Sport Utility 4D	$19,950	$25,700	$27,500
Black Label Sport Utility 4D	$20,200	$25,700	$27,600
Black Label Grand Touring Sport Utility 4D	$26,700	$32,500	$34,700

Values above are based on "Good" condition vehicles. Estimated Trade-In Values range from about $14,050 to $26,700 depending on vehicle style. Estimated Private Party Values range from about $20,700 to $32,500 depending on vehicle style. Values and prices are based on national averages and typical mileage for this model, but they can vary greatly according to mileage, condition, location, and other factors. Valid through 11/6/2026.

Trade-In Value

Trade-In Value is the amount you can expect to receive this week when trading in your vehicle at a dealership.

Private Party Value

Private Party Value is the fair price you can expect when selling your car to an individual, not to a dealer.

Fair Purchase Price

Fair Purchase Price shows what others in your area are actually paying for this vehicle.

See Full Specs for All 2020 Lincoln Aviator Styles →

Advertisement

2020 Lincoln Aviator

Depreciation

A 2020 Lincoln Aviator has depreciated $10,013 or 32% in the last 3 years and has a current resale value of $20,700 and trade-in value of $14,500.

Login or create a new account to see your vehicle depreciation forecast data.

Historical —— Forecast - - - -

2020 Lincoln Aviator

Compare up to 3 vehicles by logging in.

Log In / Sign Up

2020 Lincoln Aviator Annual Depreciation

Year	Vehicle Depreciation*	Resale Value	Trade-In Value
2023	$11,401	$30,713	$26,792
2024	$4,804	$25,909	$22,254
2025	$4,164	$21,745	$18,315
Now	$1,045	$20,700	$14,500

Unlock Forecast

2-Year Forecasted Depreciation

*Depreciation for the last 12 months of the private party resale value.

2020 Lincoln Aviator Depreciation

Annual Depreciation is an estimation of what your vehicle's value might be over time based on an average of similar vehicles. Estimations are calculated by comparing Kelley Blue Book Private Party Values of vehicles similar to yours over time, as well as forecasts from Manheim Auction data comparing current and projected auction values against current Kelley Blue Book Private Party and Trade-In Values. This is not a guarantee of actual depreciation. Local weather conditions, market factors and driver performance will also impact your vehicle's actual depreciation.

Is this information helpful?

Learn More About 2020 Lincoln Aviator Depreciation →

Already Own This Car?

Get My Car's Value →

See Cars for Sale

Calculate Your Budget With These KBB.com Tools

Car Financing 101 → Car Loan Calculator → Car Lease Calculator → Car Affordability Calculator →

Specifications

Fuel Economy
City 18 mpg/Hwy 26 mpg/Comb 21 mpg

Fuel Type
Gas

Basic Warranty
4 years or 50000 miles

Max Seating
N/A

Horsepower
400 @ 5500 RPM

Cargo Space
N/A

Read More

2020 Lincoln Aviator Safety

Safety Features & Technology

Co-Pilot360

Lincoln's basic suite of safety features includes lane-keeping assist, blind-spot warning, post-collision braking, hill start assist, rear- and forward-sensing systems, and pre-collision assist with automatic emergency braking, dynamic brake support, and pedestrian detection.

Rear- and front-camera with washer

Starting on the Reserve trim and above, the Aviator's rear and front cameras come equipped with a washer. If you're in inclement weather, or driving on dirt or snow, this is an excellent added feature.

Co-Pilot360 Plus

This feature, standard on the Grand Reserve model and above, enhances safety with other assists including Active Park Assist Plus and adaptive cruise control that automatically reads street signs.

Compare to Similar Vehicles

	 Used 2020 **Lincoln Aviator**	 Used 2020 **Cadillac XT5** See Details	 Used 2020 **Land Rover Range Rover Velar** See Details	 Used 2024 **Jeep Grand Cherokee** See Details
Price	$22,200	$21,600	$22,500	$23,800
KBB.com Rating	4.1	4.0	4.2	4.3
Consumer Rating	3.8	4.2	4.2	3.3
Fuel Economy	City 18/Hwy 26/Comb 21 MPG	City 21/Hwy 28/Comb 24 MPG	City 21/Hwy 27/Comb 23 MPG	City 19/Hwy 26/Comb 22 MPG
Fuel Type	Gas	N/A	N/A	Gas
Seating Capacity	N/A	5	5	5
Basic Warranty	4 years or 50000 miles	3 years or 36000 miles	4 years or 50000 miles	3 years or 36000 miles

2020 Lincoln Aviator Rankings

Horsepower MPG Combined Consumer Ratings

Rank	Vehicles	HP
#1	2021 Maserati Levante	424
#2	2022 Volvo XC40 Recharge	402
#3	2020 Lincoln Aviator	400
#4	2020 Jaguar I-PACE	394
#5	2020 Nissan Armada	390

More Lincoln Aviator News & Information

Luxury Midsize SUV Crossover

Only 3 of 8 Luxury SUVs Ace New Crash Test

The insurance industry is always pushing the auto industry to build safer cars. Throughout 2023, that push has taken the...

Sean Tucker | December 15, 2023

General

So Far, Autoworkers' Strike Making More Noise Than Heat

The United Auto Workers (UAW) union has been on strike for more than a month, but the strike has had...

Sean Tucker | October 20, 2023

General

UAW Strike Limiting Supplies of Some Trucks, SUVs

A nationwide autoworkers' strike heads into its second month this week, but car dealers still have an ample supply of...

Sean Tucker | October 19, 2023

FAQs

How big is the 2020 Lincoln Aviator?

The Aviator is a 3-row midsize SUV from the luxury American automaker. It's smaller than the full-size Navigator but bigger than the Lincoln Nautilus.

How many people does the 2020 Lincoln Aviator seat?

Because of the third row, the Lincoln Aviator has capacity for either six or seven. If buyers opt for a 2nd-row bench seat, then you'll be able to accommodate a 7th passenger. Note that the third row is more suitable for small children than adults, especially on long drives.

How much can the 2020 Lincoln Aviator tow?

The Lincoln Aviator has towing ability whether equipped with the gasoline or the plug-in hybrid powertrain. With the gas engine, Lincoln claims a 6,700-pound capacity, and 5,600 pounds with the hybrid engine. These numbers are impressive for a unibody SUV in this class.

Is the 2020 Lincoln Aviator a good vehicle?

Yes, the 2020 Lincoln Aviator is a good car. Its Kelley Blue Book rating of 4.1 out of 5 is within 10% of our average rating.

What is the MPG for a 2020 Lincoln Aviator?

2020 Lincoln Aviator city/highway fuel economy ratings range from 17/24 mpg to 18/26 mpg, depending on trim and equipment.

How much should a 2020 Lincoln Aviator cost?

Used 2020 Lincoln Aviator prices currently range from $22,200 for the Sport Utility 4D to $34,700 for the Black Label Grand Touring Sport Utility 4D when purchasing from a dealership, depending on a range of factors like equipment, mileage, and condition.

What's the cheapest Lincoln Aviator?

The cheapest 2020 Lincoln Aviator is the Sport Utility 4D, with a Kelley Blue Book Fair Purchase Price of $22,200.

Also from Lincoln

2020 Lincoln Continental

2020 Lincoln Corsair

2020 Lincoln MKZ

2020 Lincoln Nautilus

2020 Lincoln Navigator

2020 Lincoln Navigator L

FAQ | Contact Us | Privacy Notice | Do Not Sell or Share My Personal Information | Limit the Use of My Sensitive Personal Information | Manage Cookies | About Us | Careers | Corporate | Marketing and Advertising Solutions | Media | Site Map | KBB Brazil | KBB Canada | KBB Homes

Kelley Blue Book, a Cox Automotive Company

© 1995-2026 Kelley Blue Book Co.®, Inc. All rights reserved.

Copyrights & Trademarks | Vehicle Photos © Evox Images | Terms of Service | Linking Policy | Accessibility Statement



2020 Lincoln Aviator

MIDSIZE LUXURY SUV / 4-DOOR SUV

Award applies only to vehicles with specific headlights and built after May 2020

Crashworthiness

Small overlap front: driver-side	G
Small overlap front: passenger-side	G
Moderate overlap front: original test	G
Side: original test	G
Side: updated test	G
Roof strength	G
Head restraints & seats	G

Crash avoidance & mitigation

Headlights (varies by trim/option)	G	M
Front crash prevention: vehicle-to-vehicle		
Standard system		
Optional system		
Front crash prevention: pedestrian (day)		
Standard system		
Optional system		

Seat belts & child restraints

LATCH ease of use	A

Other available safety features

- Standard blind spot detection
- Standard lane departure warning & prevention
- Optional rear automatic braking

Key

G	Good	Superior
A	Acceptable	Advanced
M	Marginal	Basic
P	Poor	

Some ratings use a scale of Poor to Good. Others range from Basic to Superior.

Small overlap front: driver-side

Tested vehicle: **2020 Ford Explorer XLT 4-door 4wd**
Rating applies to 2020-27 models built after May 2020

The Ford Explorer was redesigned for the 2020 model year, and the Lincoln Aviator was introduced in the same model year.

Beginning with vehicles manufactured after May 2020 modifications were made to the left and right sub-frame structure to improve occupant protection in small overlap frontal crashes. (Note: information about when a specific vehicle was manufactured is on the certification label typically affixed to the car on or near the driver door.)

The second test was conducted with an Explorer built after the structural modifications were in place. In this test, the lower leg/foot rating improved to acceptable, and the overall rating improved to good.

Overall evaluation	**G**
Structure and safety cage	**G**
Driver injury measures	
Head/neck	**G**
Chest	**G**
Hip/thigh	**G**
Lower leg/foot	**A**
Driver restraints and dummy kinematics	**G**



Action shot taken during the second driver-side small overlap frontal crash test.



The dummy's position in relation to the door frame, steering wheel, and instrument panel after the second crash test indicates that the driver's survival space was maintained well.



Forces during the second crash contributed to a moderate risk of injury to the dummy's lower leg/foot.



The frontal and side curtain airbags worked well together to keep the head from coming close to any stiff structure or outside objects that could cause injury.

▶ Technical measurements for this test

Tested vehicle: **2020 Ford Explorer XLT 4-door 4wd**
Rating applies to 2020 models built before June 2020

The Ford Explorer was redesigned for the 2020 model year and the Lincoln Aviator was introduced in the same model year.

Two tests of a 2020 Explorer were conducted. In the first test as detailed here, forces recorded on the dummy's left lower leg were high, leading to a poor lower leg/foot injury rating and an overall acceptable rating. In response, Ford modified the left and right front subframe structure to improve occupant protection in small overlap frontal crashes beginning with cars manufactured after

May 2020 (note: information about when a specific vehicle was manufactured is on the certification label typically affixed to the car on or near the driver door).

In the second test of an Explorer built after the structural modifications were in place, the lower leg/foot rating improved to acceptable and the overall rating improved to good.


Overall evaluation	**A**
Structure and safety cage	**G**
Driver injury measures	
Head/neck	**G**
Chest	**G**
Hip/thigh	**G**
Lower leg/foot	**P**
Driver restraints and dummy kinematics	**G**



Action shot taken during the first driver-side small overlap frontal crash test.



The dummy's position in relation to the door frame, steering wheel, and instrument panel after the first crash test indicates that the driver's survival space was maintained well.



Although intrusion overall into the passenger's space was low, intrusion of the footrest and left portion of the toepan contributed to a likely risk of injury to the left lower leg.



The frontal and side curtain airbags worked well together to keep the head from coming close to any stiff structure or outside objects that could cause injury.

▶ Technical measurements for this test

Small overlap front: passenger-side

Tested vehicle: **2020 Ford Explorer XLT 4-door 4wd**

Rating applies to 2020-27 models built after May 2020

The Ford Explorer was redesigned for the 2020 model year, and the Lincoln Aviator was introduced in the same model year. Beginning with vehicles manufactured after May 2020 modifications were made to the left and right subframe structure to improve occupant protection in small overlap frontal crashes (Note: information about when a specific vehicle was manufactured is on the certification label typically affixed to the car on or near the driver door.)

Passenger-side small overlap frontal ratings are assigned by the Institute based on a test conducted by Ford.

Overall evaluation	**G**
Structure and safety cage	**G**
Passenger injury measures	
Head/neck	**G**
Chest	**G**
Hip/thigh	**G**
Lower leg/foot	**G**
Passenger restraints and dummy kinematics	**G**
Driver injury measures	
Head/neck	**G**
Chest	**G**
Hip/thigh	**G**
Lower leg/foot	**G**
Driver restraints and dummy kinematics	**G**

▶ Technical measurements for this test

Moderate overlap front: original test

Tested vehicle: **2020 Ford Explorer XLT 4-door 4wd**
Rating applies to 2020-23 models

The Ford Explorer was redesigned for the 2020 model year and the Lincoln Aviator was introduced in the same model year. Moderate overlap frontal ratings are assigned by the Institute based on a test conducted by Ford.

Overall evaluation	**G**
Structure and safety cage	**G**

Driver injury measures	
Head/neck	**G**
Chest	**G**
Leg/foot, left	**G**
Leg/foot, right	**G**
Driver restraints and dummy kinematics	**G**

▶ Technical measurements for this test

Side: original test

Tested vehicle: **2020 Ford Explorer XLT 4-door 4wd**
Rating applies to 2020-23 models

The Ford Explorer was redesigned for the 2020 model year and the Lincoln Aviator was introduced in the same model year. Side ratings are assigned by the Institute based on a test conducted by Ford.

Overall evaluation	**G**
Structure and safety cage	**G**
Driver injury measures	
Head/neck	**G**
Torso	**G**
Pelvis/leg	**G**
Driver head protection	**G**
Rear passenger injury measures	
Head/neck	**G**
Torso	**G**
Pelvis/leg	**G**
Rear passenger head protection	**G**

▶ Technical measurements for this test

Side: updated test

Tested vehicle: **2022 Ford Explorer XLT 4-door 4wd**

Rating applies to 2020-27 models

The Ford Explorer was redesigned for the 2020 model year and the Lincoln Aviator was introduced in the same model year.


Overall evaluation	**G**
Structure and safety cage	**G**
Driver injury measures	
Head/neck	**G**
Torso	**G**
Pelvis	**A**
Driver head protection	**G**
Rear passenger injury measures	
Head/neck	**G**
Torso	**G**
Pelvis	**G**
Rear passenger head protection	**G**




View of the vehicle just after the crash test.



View of the vehicle after the crash with doors removed, showing the side airbags and damage to the occupant compartment.



Smeared greasepaint shows where the driver dummy's head was protected from being hit by hard structures by the side airbags.



Smeared greasepaint shows where the rear passenger dummy's head was protected by the side airbag.

▶ Technical measurements for this test

Roof strength

Tested vehicle: **2020 Ford Explorer XLT 4-door 4wd**

Rating applies to 2020-23 models

Rating applies to both the Ford Explorer (tested) and the structurally similar Lincoln Aviator.

Overall evaluation	**G**
Curb weight	4,395 lbs
Peak force	24,237 lbs
Strength-to-weight ratio	5.51

Head restraints & seats

Seat type: **Power leather seat built before 2/1/2022**

Overall evaluation	**G**
Dynamic rating	**G**
Seat/head restraint geometry	**G**

▶ Technical measurements for this test


Headlights

Ratings are given for **2 different headlight variations** available on this vehicle.

(1) Trim level(s): Reserve trim equipped with Illumination package, Reserve trim equipped with Reserve 2 package, Grand Touring trim equipped with Illumination package, Grand Touring trim equipped with Grand Touring 1 package, Grand Touring trim equipped with Grand Touring 2 package, Black Label trim, Black Label Grand Touring trim

Low-beam headlight type	LED projector
High-beam headlight type	LED projector
Curve-adaptive?	Yes
High-beam assist?	Yes
Overall rating	**G**

Distance at which headlights provide at least 5 lux illumination:



Low beams

On the straightaway, visibility was good on both sides of the road. On curves, visibility was good on the sharp left and both right curves and fair on the gradual left curve.

The low beams never exceeded glare limits.

High beams

On the straightaway, visibility was good on both sides of the road. On curves, visibility was good in all 4 tests.


High-beam assist compensates for some limitations of this vehicle's low beams on both left curves.

▶ Technical measurements for this test

(2) Trim level(s): Standard trim, Reserve trim, Grand Touring trim

Low-beam headlight type	LED reflector
High-beam headlight type	LED reflector
Curve-adaptive?	No
High-beam assist?	Yes
Overall rating	**M**

Distance at which headlights provide at least 5 lux illumination:



Low beams

On the straightaway, visibility was fair on the left side of the road and inadequate on the right side. On curves, visibility was fair on the sharp left and sharp right curves and inadequate on the gradual right and gradual left curves.

The low beams never exceeded glare limits.

High beams

On the straightaway, visibility was good on the right side of the road and fair on the left side. On curves, visibility was fair on the gradual left curve and inadequate on the sharp left and both right curves.

High-beam assist compensates for some limitations of this vehicle's low beams on the straightaway and all 4 curves.

▶ Technical measurements for this test

Front crash prevention: vehicle-to-vehicle

Ratings are given for **2 different trim variations** available on this vehicle.

(1) System details

- standard Pre-Collision Assist with Automatic Emergency Braking

Package name

- standard Lincoln Co-Pilot360™

Overall evaluation

SUPERIOR

Applies to 2020-23 models

- This system meets the requirements for forward collision warning.
- In the 12 mph test, this vehicle avoided a collision.
- In the 25 mph test, this vehicle avoided a collision.

(2) System details

- optional Pre-Collision Assist with Automatic Emergency Braking

Package name

- optional Lincoln Co-Pilot360™ Assist+

Overall evaluation

SUPERIOR
WITH OPTIONAL EQUIPMENT

Applies to 2020-23 models

- This system meets the requirements for forward collision warning.
- In the 12 mph test, this vehicle avoided a collision.
- In the 25 mph test, this vehicle nearly avoided a collision.

Front crash prevention: pedestrian (day)

Ratings are given for **2 different systems** available on this vehicle.

(1) System details

- standard Pre-Collision Assist with Automatic Emergency Braking

Overall evaluation

SUPERIOR

This rating applies to all 2020-24 models

Crossing child

- In the 12 mph test, this vehicle avoided a collision.
- In the 25 mph test, impact speed was reduced by 21 mph.

Crossing adult

- In the 12 mph test, this vehicle avoided a collision.
- In the 25 mph test, this vehicle avoided a collision.

Parallel adult

- In the 25 mph test, this vehicle avoided a collision.
- In the 37 mph test, this vehicle nearly avoided a collision. A warning was issued 2 seconds before impact.

(2) System details

- optional Pre-Collision Assist with Automatic Emergency Braking

Overall evaluation

ADVANCED
WITH OPTIONAL EQUIPMENT

This rating applies to 2020-24 models on Grand Touring trimequipped with Lincoln Co-Pilot 360 Plus package,Reserve trim equipped with Lincoln Co-Pilot 360 Plus package

Crossing child

- In the 12 mph test, this vehicle avoided a collision.
- In the 25 mph test, impact speed was reduced by 19 mph.

Crossing adult

- In the 12 mph test, impact speed was reduced by 10 mph.
- In the 25 mph test, this vehicle avoided a collision.

Parallel adult


- In the 25 mph test, this vehicle avoided a collision.
- In the 37 mph test, impact speed was reduced by 19 mph. A warning was issued 2 seconds before impact.

Child seat anchors

Rating applies to 2020-22 models

Overall evaluation	**A**
Vehicle trim	Reserve
Seat type	leather

This vehicle has 4 rear seating positions with complete child seat attachment (LATCH) hardware.



G Good

A Acceptable

M Marginal

P Poor

☐ Seating positions that rely on borrowed lower anchors or have only a tether anchor available are not rated.

Tether anchor

Lower anchors

Lower anchor(s) can be borrowed from adjacent positions(s)

Details by seating position

1 **Tether anchor**

easy-to-find location

other hardware could be confused for anchor

Lower anchors

not too deep in seat

not too much force needed to attach

easy to maneuver around anchors

3 **Tether anchor**

easy-to-find location

other hardware could be confused for anchor

Lower anchors

not too deep in seat

not too much force needed to attach

easy to maneuver around anchors

4 **Tether anchor**

easy-to-find location

other hardware could be confused for anchor

Lower anchors

No hardware available

not too deep in seat

not too much force needed to attach

easy to maneuver around anchors

6 **Tether anchor**

easy-to-find location

other hardware could be confused for anchor

Lower anchors

not too deep in seat

not too much force needed to attach

easy to maneuver around anchors

▶ Technical measurements for this test

Learn about the initiative

Making roads and vehicles safer for everyone.

The **Insurance Institute for Highway Safety (IIHS)** is an independent, nonprofit scientific and educational organization dedicated to reducing deaths, injuries and property damage from motor vehicle crashes through research and evaluation and through education of consumers, policymakers and safety professionals.

The **Highway Loss Data Institute (HLDI)** shares and supports this mission through scientific studies of insurance data representing the human and economic losses resulting from the ownership and operation of different types of vehicles and by publishing insurance loss results by vehicle make and model.

Both organizations are wholly supported by these auto insurers and insurance associations.

©1996-2026, Insurance Institute for Highway Safety, Highway Loss Data Institute, 501(c)(3) organizations | Copyright information and privacy policy